



# Commercial Vehicle Inspection Report

Decal Number: RD06573  
Decal Expiry Date: 2025-Oct-07  
Inspection Number: 21510196

Inspection Result:  
**FAIL**

B07-2

FACILITY: TRIDEM SERVICES LTD / S4621 INSP. TYPE: Complete INSP. START: 2025-Sep-23 11:30 AM PDT  
INSPECTOR: ASSELS, HENRY KEITH / 200939 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Sep-23 02:00 PM PDT  
WORK ORDER #: 48284 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 02412187 VIN: 2P9BP2FL74A015919  
PLATE #: 03105J UNIT/FLEET#: 134 OWNER/LESSEE NAME: Nortrans, Freight Management LTD.  
LICENCED GVW(kg): 999999 BODY STYLE: Flat Deck Trailer ADDRESS: #7-215 Neave Rd, #7-215 Neave Rd  
VEHICLE YEAR: 2004 ODOMETER: Kelowna, British Columbia  
MAKE: MAGNUM HUB ODOMETER: V1V2L9, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE:

|                                                 |                                                                                                    |
|-------------------------------------------------|----------------------------------------------------------------------------------------------------|
| Vehicle Identification (VIN)                    | Passed                                                                                             |
| Section 1 - Power Train                         | Not Applicable                                                                                     |
| Section 2 - Suspension                          | Failed #2 LH TRAILING ARM CRACKED & ROTTED. LEVELLING VALVE LEAKING.                               |
| Section 3 - Brake System                        | Failed HIGH CAM ROTATIONS @ #1 AXLE B/S.                                                           |
| Section 3A - Air Brakes                         | Failed #1 R/H SLACK WORN, ALL HALDEX PINS & BUSHING WORN.                                          |
| Section 3H - Hydraulic Brakes                   | Not Applicable                                                                                     |
| Section 4 - Steering                            | Not Applicable                                                                                     |
| Section 5 - Instruments and Auxiliary Equipment | Not Applicable                                                                                     |
| Section 6 - Lamps                               | Passed                                                                                             |
| Section 7 - Electrical System                   | Repaired (same day) ABS LIGHT ON.                                                                  |
| Section 8 - Frame and Body                      | Failed CROSSMEMBERS CRACKED & ROTTED ABOVE BOTH AXLES. MISSING RIVETS @ FRONT WALL & CURTAIN RAIL. |
| Section 9A - Tires                              | Passed                                                                                             |
| Section 9B - Wheels                             | Passed                                                                                             |
| Section 10 - Coupling Devices                   | Passed                                                                                             |
| Section 11 - Other Vehicle Components           | Not Applicable                                                                                     |

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

| Axles | Type  | Size | Slack Adj. | Left | Right |
|-------|-------|------|------------|------|-------|
| 1     | Clamp | 30   | Automatic  | 38   | 38    |
| 2     | Clamp | 30   | Automatic  | 38   | 38    |

Comment:

## Tire Tread Depth (mm)

| Outer L | Inner L | Inner R | Outer R | Steering |
|---------|---------|---------|---------|----------|
| 12.7    | 12.7    | 12.7    | 12.7    |          |
| 11.1    | 11.1    | 10.3    | 10.3    |          |

Comment:

## Air Brake Camshaft Rotation (degrees)

| Axles | Left | Right |
|-------|------|-------|
| 1     | 105  | 105   |
| 2     | 90   | 90    |

Comment:

## Brake Lining/Pad (mm)

| Lining/Pad    | Left | Right |
|---------------|------|-------|
| Lining (Shoe) | 12   | 12    |
| Lining (Shoe) | 13   | 12    |

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

| Rotor/Drum | Left | Right |
|------------|------|-------|
| Drum       | 0.00 | 0.00  |
| Drum       | 0.00 | 0.00  |

Comment:

## Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:  
Inspector: ASSELS, HENRY KEITH Signature:

This Inspection Report was submitted to CVSE on 2025-Sep-25 03:30 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/25/2025 3:30:41 PM PDT