

EXP. APR 30/24



# Commercial Vehicle Inspection Report

Decal Number: GJ10870  
Decal Expiry Date: 2026-Apr-30  
Inspection Number: 21303393

Inspection Result: **PASS** C03-1

FACILITY: Trail Tire Vernon / S20233 INSP. TYPE: Complete INSP. START: 2025-Apr-07 12:31 PM PDT  
INSPECTOR: COX, NEIL FREDERICK / 301319 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2025-Apr-07 02:58 PM PDT  
WORK ORDER #: IN002898 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 12641709 VIN: 1XPHD48X7DD177450  
PLATE #: ML7257 UNIT/FLEET#: 102 OWNER/LESSEE NAME: TAYLOR PRO TRAINING LTD., TAYLOR PRO TRAINING LTD.  
LICENCED GVW(kg): 33000 BODY STYLE: Truck Tractor ADDRESS: 102-4700 23rd STREET  
VEHICLE YEAR: 2013 ODOMETER: 808807 KM Vernon, British Columbia  
MAKE: PETERBILT HUB ODOMETER: V1T 4K9, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) SECOND AXEL R/S SLACK REPAIRED.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxilliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) DEF TANK STRAPS CHANGED.
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	12	22	9			9	✓
2	Clamp	30L	Automatic	22	24	19	19	19	19	
3	Clamp	30L	Automatic	20	22	19	19	19	19	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	31	35	Lining (Shoe)	19	18	Drum		
2	60	45	Lining (Shoe)	16	17	Drum		
3	22	54	Lining (Shoe)	19	17	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Signature: Road Tester:

This Inspection Report was submitted to CVSE on 2025-Apr-07 03:59 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.  
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement  
CVSED014  
4/7/2025 3:59:25 PM PDT