



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	WEST ARM TRUCK LINES LTD.		
Address:	UNIT C 6812 6 ST S.E.		
City:	CALGARY	Province:	AB
		Postal Code:	T2H2K4
Telephone Number:	(403) 236-0912		
Vehicle Identification Number:	5V8VA53247M704876		
Make:	vanguard	Model:	vip4000
Year:	2007	Unit Number:	236
Odometer:	4298 KM	Licence Plate Number:	W19822
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	TCB Trailer Services and Repair Ltd	Facility Number:	16140
Inspection Technician Name:	David Richards	Technician Number:	B9840
Inspection Technician Signature:			
Inspection Date:	2024/11/30		

Commercial Vehicle Inspection Report

Decal Number: GK91365
 Decal Expiry Date: 2026-Oct-31
 Inspection Number: 21543435

Inspection Result:
PASS

FACILITY: MOTOR-WAY TRUCK AND TRAILER / S15040
INSPECTOR: MROKE, GURPAL SINGH / 108739
WORK ORDER #: 23571
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Oct-24 10:00 AM PDT
INSP. COMPLETE: 2025-Oct-24 12:00 PM PDT

VEHICLE JUR: Alberta
PLATE #: W19822
REGISTERED GVW(kg): 999999
VEHICLE YEAR: 2007
MAKE: VANGUARD
MODEL:
REGI:
UNIT/FLEET#: 236
BODY STYLE: Trailer
ODOMETER:
HUB ODOMETER: 36801 KM
BRAKE TYPE: Air
FUEL TYPE: Not Applicable
VIN: 5V8VA53247M704876
OWNER/LESSEE NAME: WEST, ARM TRUCK LINES LTD
ADDRESS: UNIT C 6812 6 ST SE
 CALGARY, Alberta
 T2H2K4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPLACED ROOF BOW , FIXED BOTTOM DOOR POST CRACKS ,
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	7	6	8	11	
2	Clamp	30	Automatic	45	45	6	12	7	7	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	75	70	Lining (Shoe)	17	17	Drum	420.89	420.95
2	65	70	Lining (Shoe)	18	16	Drum	420.50	420.56

Comment:

Inspection Comments:
 Has this Vehicle been road tested? No
Inspector: MROKE, GURPAL SINGH
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Oct-24 04:14 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement