



Commercial Vehicle Inspection Report

Decal Number: GJ72593
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21425120

Inspection Result:

PASS

FACILITY: MACK SALES & SERVICES OF NANAIMO LTD. / S12380
INSPECTOR: BOYCHUK, RICHARD STEPHEN / 111470
WORK ORDER #: 393477

INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSR. REASON: Semi-annual

INSR. START: 2025-Jul-10 11:30 AM PDT
INSR. COMPLETE: 2025-Jul-14 03:01 PM PDT

VEHICLE JUR: British Columbia
PLATE #: SF5889

REGI: 11717123
UNIT/FLEET#: WT-13

VIN: 1FVNFECB6WP988808
OWNER/LESSEE NAME: HAZELWOOD CONSTRUCTION, SERVICES INC.
ADDRESS: 1930 BOLLINGER ROAD
Nanaimo, British Columbia
V9S5W9, Canada

LICENCED GVW(kg): 23500
VEHICLE YEAR: 1998
MAKE: FREIGHTLIN
MODEL:

BODY STYLE: Tank
ODOMETER: 83828 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) R1 SHOCK REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) R2 , R3 SLACK ADJUSTERS REPLACED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Not Applicable
Section 9B - Wheels	Not Applicable
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Stack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	32	32	16			16	✓
2	Clamp	30	Automatic	33	33	12	7	7	7	
3	Clamp	30	Automatic	33	33	8	13	20	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	75	75
2	90	90
3	90	90

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	13	13
Lining (Shoe)	12	12
Lining (Shoe)	12	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: BOYCHUK, RICHARD STEPHEN

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-14 03:02 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP of the Commercial Vehicle Safety Enforcement

CVSE0014

7/14/2025 3:02:10 PM PDT