



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GF24439
Decal Expiry Date: 2025-Aug-31
Inspection Number: 21236905

Inspection Result: C69

PASS

FACILITY:	PIER PROPERTY INC. / S6855	INSP. TYPE:	Complete	INSP. START:	2025-Feb-13 07:00 AM PST
INSPECTOR:	SON, JAE / 200353	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Feb-13 11:49 AM PST
WORK ORDER #:	VCRR-0080081	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	12984481	VIN:	1XPBDP9X2LD689525
PLATE #:	NK7457	UNIT/FLEET#:	3412V	OWNER/LESSEE NAME:	TRANSX, LTD
LICENCED GVW(kg):	46500	BODY STYLE:	Truck Tractor	ADDRESS:	2595 INKSTER BLVD, 2595 INKSTER BLVD WINNIPEG, Manitoba R3C2E6, Canada
VEHICLE YEAR:	2020	ODOMETER:	331186 KM		
MAKE:	PETERBILT	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Not Applicable	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPLACED RS LOW BEAM LIGHT
Section 7 - Electrical System	Repaired (same day)	REPAIRED TRAILER CORD LIGHTS
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	ADJUSTED 5TH WHEEL
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	32	32	20			20	✓
2	Clamp	30L	Automatic	38	38	24	24	24	24	
3	Clamp	30L	Automatic	40	40	24	24	24	24	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	40
2	55	50
3	65	65

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	16	16
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SON, JAE

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Feb-13 11:49 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement

CVSED014

2/13/2025 11:49:47 AM PST

W. J. H. H. H.