



Commercial Vehicle Inspection Report

Decal Number: GF24406
Decal Expiry Date: 2025-Jun-30
Inspection Number: 21172314

Inspection Result:
PASS

C69-2

FACILITY:	PIER PROPERTY INC. / S6855	INSP. TYPE:	Complete	INSP. START:	2024-Dec-09 10:00 AM PST
INSPECTOR:	SON, JAE / 200353	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2024-Dec-09 02:42 PM PST
WORK ORDER #:	VCRR-0078824	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	13084181	VIN:	1XPBDP9XXLD689532
PLATE #:	NV2246	UNIT/FLEET#:	3502V	OWNER/LESSEE NAME:	TRANSX LTD, TRANSX LTD
LICENCED GVW(kg):	46500	BODY STYLE:	Truck Tractor	ADDRESS:	2595 INKSTER BLVD, 2595 INKSTER BLVD WINNIPEG, Manitoba R3C2E6, Canada
VEHICLE YEAR:	2020	ODOMETER:	272263 KM		
MAKE:	PETERBILT	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACED #2 AXLE LS AIRBAG
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPLACED 2 WORK LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Repaired (same day) ADJUSTED 5TH WHEEL
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	32	34	12			8	✓
2	Clamp	30L	Automatic	38	38	12	13	9	8	
3	Clamp	30L	Automatic	38	40	24	24	24	24	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	35	35	Lining (Shoe)	19	19	Drum			
2	40	40	Lining (Shoe)	19	19	Drum			
3	45	50	Lining (Shoe)	18	17	Drum			
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: SON, JAE Signature:

This Inspection Report was submitted to CVSE on 2024-Dec-09 02:43 PMPST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.