

Commercial Vehicle Inspection Report

Decal Number: GC19273 Decal Expiry Date: 2025-Sep-30 Inspection Number: 21078082 PASS

FACILITY: NSPECTOR: NORK ORDER #:	PIER PROPERTY INC. / S6855 SON, JAE / 200353 VCRR-0077659	INSP. TYPE: INSP. CLASS: INSP. REASON:	Complete Class 3 - Trailer and Se Annual	INSP. START: mi-Trailer INSP. COMPLET	2024-Sep-19 1 E: 2024-Sep-19 (
/EHICLE JUR:	Alberta	REGI:	and the second	VIN:	1GRAA6017VW060901	
PLATE #:	9785-15	UNIT/FLEET#:	0111008	OWNER/LESSEE NAME:	TRANSX LTD, TRANSX L	rD
JCENCED GVW(kg) : 0	BODY STYLE:	Semi Trailer	ADDRESS:	285115 61 AVE	
/EHICLE YEAR:	1997	ODOMETER:			CALGARY, Alberta	
MAKE:	GREAT DANE	HUB ODOMETER:			T2P 2G6, Canada	
MODEL:	REEFER	BRAKE TYPE:	Air		and the second s	
		FUEL TYPE:	Not Applicable			
Vehicle Identification (VIN)		Passed				Sugar Com
Section 1 - Power Train		Not Applicable				
Section 2 - Suspension		Passed				
Section 3 - Brake System		Not Applicable				
Section 3A - Air Brakes		Passed				
Section 3H - Hydraulic Brakes		Not Applicable				
Section 4 - Steering		Not Applicable				
Section 5 - Instru Equipment	ments and Auxiliary	Not Applicable				
Section 6 - Lamps		Passed			and the second	And and a second second
Section 7 - Electrical System		Passed				
Section 8 - Frame and Body		Passed				
Section 9A - Tires	and the second se	Passed				
Section 9B - Wheels		Passed				
Section 10 - Coupling Devices		Passed				
Section 11 - Other Vehicle Components		Not Applicable				
Vir Brake Chambe	r Type, Size and Push Rod Stro	ke (mm)	Tire Tread De	epth (mm)		
Axles	Type Size Slack	Adj. Left I	Right Outer L	Inner L Inner	R Outer R	Steering
1 0	Clamp 30 Autor	natic 34	36 16	15 16	16	
			Comment:			
Comment:						
	ft Rotation (degrees)	Brake Lining/Pad (mm)	Rotor Thicknes	ss or Drum Inside Diamet	er (mm)
	ft Rotation (degrees) Left Right	Brake Lining/Pad (Lining/Pad			ss or Drum Inside Diamet /Drum Left	er (mm) Right
\ir Brake Camshaf		Lining/Pa	d Left		/Drum Left	
∖ir Brake Camshaf Axles	Left Right		d Left	Right Rotor/ 14 Dru Comment: Air I	/Drum Left	Right erformea. Rotor
۵ir Brake Camshaf Axles 1	Left Right	Lining/Pac Lining (Sho	d Left	Right Rotor/ 14 Dru Comment: Air I	/Drum Left um Brake Camshaft Rotation pe	Right erformea. Rotor
¥ir Brake Camshaf Axles 1 Comment:	Left Right 65 85	Lining/Pac Lining (Sho	d Left	Right Rotor/ 14 Dru Comment: Air I	/Drum Left um Brake Camshaft Rotation pe	Right erformea. Rotor
મંr Brake Camshaf Axles 1	Left Right 65 85	Lining/Pac Lining (Sho	d Left	Right Rotor/ 14 Dru Comment: Air I	/Drum Left um Brake Camshaft Rotation pe	Right erformea. Rotor

OTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

he personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection ind for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement XVSE0014

1/19/2024 3:21:08 PM PDT

