



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GD32787
Decal Expiry Date: 2025-Jul-31
Inspection Number: 21018549

Inspection Result:

PASS

FACILITY: MODERN DIESEL TRUCK REPAIR LTD. / S15400
INSPECTOR: DHALIWAL, HARPINDER SINGH / 300434
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2024-Jul-27 09:00 PM PDT
INSP. COMPLETE: 2024-Jul-27 10:30 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 36817K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2023
MAKE: VANGUARD
MODEL:

REGI: 14067932
UNIT/FLEET#:
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 5V8VC5324PT307703
OWNER/LESSEE NAME: PRODUCT LINE, HOLDINGS AND L
ADDRESS: 4-588 ANNANCE CRT
Delta, British Columbia
V3M6Y8 Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) REPLACED BRAKE SHOE And drum on axle 1 and 2 both side
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Shock Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	35	14	14	14	14	
2	Clamp	30	Automatic	35	35	10	10	10	10	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	25	25
2	25	25

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	21
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: DHALIWAL, HARPINDER SINGH
Road Test Date:
Road Tester:
Signature:

This Inspection Report was submitted to CVSE on 2024-Jul-28 04:00 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/28/2024 4:00:49 PM PDT

