



Commercial Vehicle Inspection Report

Decal Number: GH11068
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21308651

D03-1

Inspection Result:
PASS

FACILITY:	LITTLE DIESEL SHOP INC. / S16360	INSP. TYPE:	Complete	INSP. START:	2025-Apr-07 09:30 AM PDT
INSPECTOR:	Kinakin, Nik / 300543	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Apr-11 08:16 AM PDT
WORK ORDER #:	8638	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	02230896	VIN:	2HSCNSCR84C027294
PLATE #:	ND0482	UNIT/FLEET#:	9	OWNER/LESSEE NAME:	MTS, Transport LTD
PERMITTED GVW(kg):	33000	BODY STYLE:	Truck Tractor	ADDRESS:	2654 Norris RD
VEHICLE YEAR:	2004	ODOMETER:	598206 KM		Kelowna, British Columbia
MAKE:	INTERNATNA	HUB ODOMETER:			V1X7L9, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	replaced loose #2 axle input yoke nut and leaking #2 wheel seals at time of inspection.
Section 2 - Suspension	Repaired (same day)	replaced #2LH and #3LH air bags and #2 spring eye bushings at time of inspection.
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	RH work light repaired at time of inspection.
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	secured loose RH front fender at time of inspection.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	5th wheel adjusted
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	38	38	6			9	✓
2	Clamp	30	Automatic	32	32	17	17	17	15	
3	Clamp	30	Automatic	38	38	13	11	12	12	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	90	80	Lining (Shoe)		12	12	Drum		
2	45	50	Lining (Shoe)		15	15	Drum		
3	50	50	Lining (Shoe)		15	15	Drum		

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____

Inspector: Kinakin, Nik **Signature:** 

This Inspection Report was submitted to CVSE on 2025-Apr-11 08:17 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement