

## **Commercial Vehicle** Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GJ62509 2025-Nov-30 21360622

Inspection Result:

**PASS** 

FACILITY:	HARKO HEAVY DUTY LTD. / S17130	INSP. TYPE:	Complete		INSP. START:	2025-May-22 08:16 AM PD	
INSPECTOR:	Hawrylenko, Quinton Boyd / 2011	INSP. CLASS:	Class 2 - Heavy Vehicle with 5501 kg or more	LGVW	INSP. COMPLETE		
WORK ORDER #:		INSP. REASON:	Semi-annual				
VEHICLE JUR:	British Columbia	REGI:	13847593	VIN:		1FDFF6LT7MDA01576	
PLATE #:	RV9587	UNIT/FLEET#:	17-152	OWNER	LESSEE NAME:	Twin Valley Contracting, LTD	
LICENCED GVW(kg): 19978		BODY STYLE:	Dump Truck	ADDRES		489 CHILCOTIN RD	
VEHICLE YEAR:	2021	ODOMETER:	81376 KM			Kamloops, British Columbia	
MAKE:	FORD	HUB ODOMETER:				V2H 1G4, Canada	
MODEL:		BRAKE TYPE:	Hydraulic			VZII 164, Callada	
		FUEL TYPE:	Diesel				
Vehicle Identificati	ion (VIN)	assed					
Section 1 - Power Train		assed					
0 41 0 0		epaired (same day)	LH REAR SHOCK MOUNT E	ENT			
Section 3 - Brake System		assed		LIVI.			
Section 3H - Hydra	ulic Brakes Pa	assed					
Section 4 - Steering		epaired (same day)	RH LOWER TIE ROD END.				
Section 5 - Instrum Equipment	ents and Auxiliary	assed	The state of the s				
Section 6 - Lamps	R	epaired (same day)	LH HEADLIGHT MARKER.				
Section 7 - Electric	al System Pa	issed					
Section 8 - Frame	and Body Pa	assed					
Section 9A - Tires	Pa	ssed					
Section 9B - Whee	ls Pa	ssed					
Section 10 - Coupli	ing Devices Pa	ssed					
		ssed					

Tire Tread Depth (mm)				Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	12			12	~	Pad	9	9	Rotor	36.00	36.00
2	13	12	13	13		Pad	10	10	Rotor	36.00	36.00
Comme	nt:					Comment:	-		Comment:	or trienge generality	

Inspection Comments:

Inspector:

Has this Vehicle been road tested? No Road Test Date:

Signature:

Road Tester:

Hawrylenko, Quinton Boyd

This Inspection Report was submitted to CVSE on 2025-May-22 03:16 PMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

The property of the property o

.: the large s and the second control of राज्याका कुरू रहे छन्। अस्तराज्य हर स<mark>्व</mark>ातका सह Roth the control the above 1.3.8 + jg + 2.4. (\*) Bright of the section and has been de parama (green) consist and seve Typica per grander , the tings with the second Calman Garage te cambination and the second DAL प्रमुख्याद - <u>शिक्षक वित्र</u> gramma and same gar a paper a recovery.

Michael - Communication - Comm

1.0

47.34

5 65 A 4

1.3

्राच्या कुरुका स्थाप्त । अनुस्था स्थापना स्थापना । प्राचीती हो जिल्लामा स्थापना स्थापना स्थापना ।

บาร์มูห์เกิดเรา

\$10**9**1604

green garage

1964 1 1 1 1 1 1 1 1

J. 1.

in the state of