



# Commercial Vehicle Inspection Report

Decal Number: GK67034  
Decal Expiry Date: 2026-Sep-30  
Inspection Number: 21491651

Inspection Result: **PASS**

105-3

FACILITY: TRIDEM SERVICES LTD. / S10410 INSP. TYPE: Complete INSP. START: 2025-Sep-09 07:52 AM PDT  
INSPECTOR: Holder, Brett Robert / 300564 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Sep-10 10:52 AM PDT  
WORK ORDER #: 30561 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 10350409 VIN: 2BGF10288WS049416  
PLATE #: 30256L UNIT/FLEET#: 53D65 OWNER/LESSEE NAME: TAYLOR PRO COLLEGE LTD., TAYLOR PRO COLLEGE LTD.  
LICENCED GVW(kg): 999999 BODY STYLE: Van Trailer ADDRESS: 2654 NORRIS RD  
VEHICLE YEAR: 1998 ODOMETER: Kelowna, British Columbia  
MAKE: GREAT DANE HUB ODOMETER: V1X7L9, Canada  
MODEL: BRAKE TYPE: Air FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) INSTALLED BUMPER REFLECTIVE TAPE
Section 6 - Lamps	Repaired (same day) INSTALLED MANDITORY REAR ID LIGHTS AND CLEARANCE LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPAIRED LOOSE, HINGE, DOOR CAM MOUNT AND LATCHES. (CAUTION* DOORS ROTTEN)
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) REPAIRED L AND R #1 WHEEL SEALS LEAKING
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	38.1	38.1
2	Clamp	30	Automatic	38.1	38.1

Comment:

### Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8	8	9	9	
11	11	4	4	

Comment:

### Air Brake Camshaft Rotation (degrees)

Axes	Left	Right
1	85	50
2	60	85

Comment:

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	14
Lining (Shoe)	15	16

Comment:

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:  
Inspector: Holder, Brett Robert Signature:

This Inspection Report was submitted to CVSE on 2025-Sep-10 10:53 AMPDT  
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCAVP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/10/2025 10:53:07 AMPDT