



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GK55739
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21475403

Inspection Result:
PASS

FACILITY:	BAYSIDE MACHINE SERVICES / 58760	INSP. TYPE:	Complete	INSP. START:	2025-Aug-28 08:00 AM PDT
INSPECTOR:	Gorle, Brian James / 203504	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Aug-29 11:54 AM PDT
WORK ORDER #:	15482	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	10887752	VIN:	1M1AW07YXDM035593
PLATE #:	PD4600	UNIT/FLEET#:	14	OWNER/LESSEE NAME:	Top Shelf Feeds Inc., Top Shelf Feeds Inc.
PERMITTED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	2800 Roberts Rd., 2800 Roberts Rd.
VEHICLE YEAR:	2013	ODOMETER:	705021 KM		Duncan, British Columbia
MAKE:	MACK	HUB ODOMETER:			V8L6W3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Repaired (same day)	Rear shock lower bolts replaced
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	Customer Advised Axel # 3 right tires need replacing soon
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	29	31	6.31			7.48	✓
2	Clamp	30L	Automatic	33	34	12.42	7.98	12.66	10.28	
3	Clamp	30L	Automatic	34	34	5.28	5.53	3.87	3	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	29	88	Lining (Shoe)	19	15	Drum		
2	71	89	Lining (Shoe)	14	13	Drum		
3	56	64	Lining (Shoe)	17	17	Drum		

Comment:

Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: Gorle, Brian James Signature:

This Inspection Report was submitted to CVSE on 2025-Aug-29 11:55 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

2/5/2014

1/28/2025 11:55:28 AM PDT