

D10-1



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GH92340
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21275704

Inspection Result:
PASS

| | | | | | |
|----------------------------|----------------------------|----------------------|------------------------------------|---------------------------|--|
| FACILITY: | OCEAN TRAILER / S8173 | INSP. TYPE: | Complete | INSP. START: | 2025-Mar-18 06:00 AM PDT |
| INSPECTOR: | Mihajlovic, Dejan / 202707 | INSP. CLASS: | Class 3 - Trailer and Semi-Trailer | INSP. COMPLETE: | 2025-Mar-18 07:00 AM PDT |
| WORK ORDER #: | WO53310 | INSP. REASON: | Annual | | |
| VEHICLE JUR: | Alberta | REGI: | | VIN: | LJRC41372F1009696 |
| PLATE #: | 4XV4410 | UNIT/FLEET#: | 66307 | OWNER/LESSEE NAME: | C KEAY INVESTMENTS LTD, C KEAY INVESTMENTS LTD |
| LICENCED GWW(kg): 0 | | BODY STYLE: | | ADDRESS: | 234136 84 ST SE, 234136 84 ST SE |
| VEHICLE YEAR: | 2015 | ODOMETER: | | | ROCKY VIEW, Alberta |
| MAKE: | CIMC | HUB ODOMETER: | 373006 KM | | T1X0K2, Canada |
| MODEL: | CHASSIS | BRAKE TYPE: | Air | | |
| | | FUEL TYPE: | Not Applicable | | |

| | |
|--|----------------|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Not Applicable |
| Section 2 - Suspension | Passed |
| Section 3 - Brake System | Passed |
| Section 3A - Air Brakes | Passed |
| Section 3H - Hydraulic Brakes | Not Applicable |
| Section 4 - Steering | Not Applicable |
| Section 5 - Instruments and Auxiliary Equipment | Not Applicable |
| Section 6 - Lamps | Passed |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Passed |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Not Applicable |

| Air Brake Chamber Type, Size and Push Rod Stroke (mm) | | | | Tire Tread Depth (mm) | | | | | | |
|---|-------|------|------------|-----------------------|-------|---------|---------|---------|---------|----------|
| Axles | Type | Size | Slack Adj. | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering |
| 1 | Clamp | 30 | Automatic | 44.5 | 44.5 | 11.9 | 9.5 | 11.9 | 11.9 | |
| 2 | Clamp | 30 | Automatic | 44.5 | 44.5 | 11.9 | 15.9 | 15.1 | 12.7 | |
| 3 | Clamp | 30 | Automatic | 44.5 | 44.5 | 9.5 | 9.5 | 9.5 | 9.5 | |

Comment:

Comment:

| Air Brake Camshaft Rotation (degrees) | | | Brake Lining/Pad (mm) | | | Rotor Thickness or Drum Inside Diameter (mm) | | |
|---------------------------------------|------|-------|-----------------------|------|-------|--|------|-------|
| Axles | Left | Right | Lining/Pad | Left | Right | Rotor/Drum | Left | Right |
| 1 | 35 | 30 | Lining (Shoe) | 19.1 | 19.1 | Drum | | |
| 2 | 30 | 30 | Lining (Shoe) | 19.1 | 19.1 | Drum | | |
| 3 | 30 | 30 | Lining (Shoe) | 19.1 | 19.1 | Drum | | |

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Yes
 Inspector: Mihajlovic, Dejan
 Road Test Date: _____ Road Tester: _____
 Signature: *Dejan Mihajlovic*

This Inspection Report was submitted to CVSE on 2025-Mar-18 03:27 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSED014

3/18/2025 3:27:14 PM PDT