



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ79716
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21363660

Inspection Result: **PASS** *D12-1*

FACILITY: GROVE TRUCK REPAIRS LTD. / S20376
INSPECTOR: THIND, PUNEET PAL SINGH / 300403
WORK ORDER #: khaliis

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2025-May-24 03:00 PM PDT
INSP. COMPLETE: 2025-May-24 05:30 PM PDT

VEHICLE JUR: British Columbia
PLATE #: WB3220
LICENCED GVW(kg): 46500
VEHICLE YEAR: 2011
MAKE: FREIGHTLIN
MODEL:

REGI: 11317322
UNIT/FLEET#: 731
BODY STYLE: Truck Tractor
ODOMETER: 1813268 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

VIN: 1FUJGLDR6BSAW9398
OWNER/LESSEE NAME: KHALIS TRANSPORT INC, ..
ADDRESS: 6439 140A ST
Surrey, British Columbia
V3W 9H9, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	FIX ABS
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Repaired (same day)	REPLACE STEERINGBOX SEAL
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	32	32
2	Clamp	30L	Automatic	36	36
3	Clamp	30L	Automatic	36	35

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	13			13	✓
2	10	10	10	10	
3	7	6	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	43	43
2	60	43
3	41	41

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
1	Lining (Shoe)	17	17
2	Lining (Shoe)	14	18
3	Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
1	Drum		
2	Drum		
3	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: THIND, PUNEET PAL SINGH

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-24 08:08 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSED014

5/24/2025 8:08:31 PM PDT