



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GD35091
Decal Expiry Date: 2025-Aug-31
Inspection Number: 21050784

Inspection Result:

PASS

FACILITY: OK TRUCK CENTRE 2015 / S11720 INSP. TYPE: Complete INSP. START: 2024-Aug-24 09:00 AM PDT
INSPECTOR: ROSIN, JASON EDWIN / 112645 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2024-Aug-27 10:00 AM PDT
WORK ORDER #: 69978 INSP. REASON: Annual

VEHICLE JUR: British Columbia REG: 12802821 VIN: 2M5120855K1182718
PLATE #: 78014K UNIT/FLEET#: SFB04 OWNER/LESSEE NAME: Sunfire Consulting Ltd. DIV Of Sunfire Transport
LICENCED GVW(kg): 0 BODY STYLE: Flat Deck Trailer ADDRESS: PO Box 932
VEHICLE YEAR: 2018 ODOMETER: Osoyoos, British Columbia
MAKE: MANAC HUB ODOMETER: V0H1V0, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) Change #1R & 2R cam tubes & Clevis bushings. Change #1R s-cam.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) Install missing front right amber reflector.
Section 7 - Electrical System	Repaired (same day) Change ABS ECU
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	39	37	10.99	10.81	11.13	12.32	
2	Clamp	30	Automatic	35	37	7.32	8.12	6.91	8.31	
Comment:						Comment:				
Air Brake Camshaft Rotation (degrees)				Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles		Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1		81	63	Lining (Shoe)	12	17	Drum			
2		89	75	Lining (Shoe)	12	15	Drum			
Comment:				Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: ROSIN, JASON EDWIN Signature:

This Inspection Report was submitted to CVSE on 2024-Aug-27 11:53 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CV530014

8/27/2024 11:53:30 AM PDT