



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ79716
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21363660

Inspection Result:

PASS

D12-1

FACILITY:	GROVE TRUCK REPAIRS LTD. / S20376	INSP. TYPE:	Complete	INSP. START:	2025-May-24 03:00 PM PDT
INSPECTOR:	THIND, PUNEET PAL SINGH / 300403	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-May-24 05:30 PM PDT
WORK ORDER #:	khalis	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	11317322	VIN:	1FUJGLDR6BSAW9398
PLATE #:	WB3220	UNIT/FLEET#:	731	OWNER/LESSEE NAME:	KHALIS TRANSPORT INC, ..
LICENCED GVW(kg):	46500	BODY STYLE:	Truck Tractor	ADDRESS:	6439 140A ST Surrey, British Columbia V3W 9H9, Canada
VEHICLE YEAR:	2011	ODOMETER:	1813268 KM		
MAKE:	FREIGHTLIN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) FIX ABS
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) REPLACE STEERINGBOX SEAL
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Tire Tread Depth (mm)							
				Left	Right	Outer L	Inner L	Inner R	Outer R	Steering	
1	Clamp	24L	Automatic	32	32	13			13		✓
2	Clamp	30L	Automatic	36	36	10	10	10	10		
3	Clamp	30L	Automatic	36	35	7	6	8	8		

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)				Rotor Thickness or Drum Inside Diameter (mm)			
			Lining/Pad	Left	Right	Rotor/Drum	Left	Right		
1	43	43	Lining (Shoe)	17	17	Drum				
2	60	43	Lining (Shoe)	14	18	Drum				
3	41	41	Lining (Shoe)	19	19	Drum				

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: THIND, PUNEET PAL SINGH

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-24 08:08 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSE014

5/24/2025 8:08:31 PM PDT