E03-2

BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GH55219
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21262369

Inspection Result: **PASS**

FACILITY:	BILL'S HEAVY DUTY / S0243	**INSP. TYPE:**	Complete	**INSP. START:**	2025-Mar-05 10:53 AM PST
INSPECTOR:	GEBHART, NICHOLAS TYLER / 202083	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2025-Mar-07 12:53 PM PST
		INSP. REASON:	Annual		
WORK ORDER #:	RB19943				

VEHICLE JUR:	Alberta	**REGI:**		**VIN:**	1UYVS2539FG184810
PLATE #:	5MA698	**UNIT/FLEET#:**	53H31	**OWNER/LESSEE NAME:**	OVERLAND WEST FRIEGHT LINES LTD,
LICENCED GVW(kg):	0	**BODY STYLE:**	Van	**ADDRESS:**	15811 112 AVE NW
VEHICLE YEAR:	2015	**ODOMETER:**			EDMONTON, Alberta
MAKE:	UTILITY	**HUB ODOMETER:**	61039 KM		T5M 2V9, Canada
MODEL:	VS2DX	**BRAKE TYPE:**	Air		
		FUEL TYPE:	Not Applicable		

Vehicle Identification (VI)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	REPLACE 1L, 2R LEAF SPRINGS
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACE 2L WHEEL SEAL
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIR TAIL LIGHTS
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	50	45
2	Clamp	30	Automatic	30	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
7	10	9	7	
10	8	9	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	80	60
2	85	85

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	13
Lining (Shoe)	13	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: GEBHART, NICHOLAS TYLER **Signature:**

This Inspection Report was submitted to CVSE on 2025-Mar-07 12:54 PM PST
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSB0014
3/7/2025 12:54:12 PM PST