



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: **GC59844**
Decal Expiry Date: **2025-Dec-31**
Inspection Number: **21388517**

Inspection Result:

PASS

FACILITY: CULLEN DIESEL POWER LTD. / S16800
INSPECTOR: BELLAMY, BRODY JON-HENRY / 201409
WORK ORDER #: 8438

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2025-Jun-12 12:44 PM PDT
INSP. COMPLETE: 2025-Jun-12 01:44 PM PDT

VEHICLE JUR: British Columbia
PLATE #: KJ5999
LICENCED GVW(kg): 44000
VEHICLE YEAR: 2005
MAKE: FREIGHTLIN
MODEL:

REGI: 02951795
UNIT/FLEET#: HT129
BODY STYLE: Dump Truck
ODOMETER: 29684 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

VIN: 1FVHALCK85DV08615
OWNER/LESSEE NAME: TRANSPORT L, LITTLE MOUNTAIN
ADDRESS: 25-1343 ALBERNI HWY
Parksville, British Columbia
V9P2B9, Canada

Unit #129

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACED 3R BRAKES AND DRUM, 3L PIGGY BACK, AND 2R PIGGY BACK.
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	32	32
2	Clamp	30	Automatic	35	34
3	Clamp	30	Automatic	36	32

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	11.1			11.9	✓
	9.5	7.9	8.7	9.5	
	7.9	4.8	3.2	5.8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	80	70
2	90	75
3	85	35

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
	Lining (Shoe)	15	16
	Lining (Shoe)	14	16
	Lining (Shoe)	13	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. NEW DRUM 3R

Inspection Comments:

Has this Vehicle been road tested? **No**

Road Test Date:

Road Tester:

Inspector: **BELLAMY, BRODY JON-HENRY**

Signature:

This Inspection Report was submitted to CVSE on 2025-Jun-12 01:45 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE014

6/12/2025 1:45:42 PM PDT