



Commercial Vehicle
Inspection Report

Decal Number: GK46249
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21480813

Inspection Result:
PASS

FACILITY: L M DIESELS TRUCK & TRAILER REPAIR LTD. / S14470
INSPECTOR: BRAR, LAKHWINDER SINGH BRAR / 300717
WORK ORDER #:

INSR. TYPE: Complete
INSR. CLASS: Class 3 - Trailer and Semi-Trailer
INSR. REASON: Annual

INSR. START: 2025-Sep-01 01:45 PM PDT
INSR. COMPLETE: 2025-Sep-01 03:10 PM PDT

VEHICLE JUR: British Columbia
PLATE #:

REGI: 00558623
UNIT/FLEET#: PF3433
VIN: 2LDPA48251C035622
OWNER/LESSEE NAME: PIKE ENTERPRISES LTD, PIKE ENTERPRISES LTD
ADDRESS: 18991 96 AVE, 18991 96 AVE
Surrey, British Columbia
V4N3P3, Canada

LICENCED GVW(kg): 999989
VEHICLE YEAR: 2001
MAKE: LOAD KING
MODEL:

BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) XL2 D/S BRAKE AND DRUM REPLACED
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) REFLECTOR TAPE AT REAR
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Stack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	36	12.2	14.2	14.2	14	
2	Clamp	30	Automatic	35	36	12	8.2	10.2	13	
3	Clamp	30	Automatic	37	36	12	14	11	14	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	31	32	Lining (Shoe)	21	21	Drum		
2	30	41	Lining (Shoe)	21	19	Drum		
3	42	52	Lining (Shoe)	19	17	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date:
Inspector: BRAR, LAKHWINDER SINGH BRAR Signature:

This Inspection Report was submitted to CVSE on 2025-Sep-01 09:48 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.