

E15-1



Commercial Vehicle Inspection Report

Decal Number: GK33687
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21430122

Inspection Result:
PASS

FACILITY:	NORTH YARDS CONTRACTING LTD / S15000	INSP. TYPE:	Complete	INSP. START:	2025-Jul-17 05:00 PM PDT
INSPECTOR:	James, Mark / 202564	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jul-18 09:58 AM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	12931468	VIN:	5PVNJ8JT9D4S54248
PLATE #:	9Y1M6V	UNIT/FLEET#:		OWNER/LESSEE NAME:	dake contracting ltd, dake contracting
LICENCED GVW(kg):	11790	BODY STYLE:	Flat Deck	ADDRESS:	1980 centennial way, po box 589
VEHICLE YEAR:	2013	ODOMETER:	3164 KM		Squamish, British Columbia
MAKE:	HINO	HUB ODOMETER:			v8b0a5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) all new tires
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	16	Automatic	25.4	25.4	15			15	✓
2	Clamp	30	Automatic	28.6	28.6	18	18	18	18	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	30	Lining (Shoe)	21	21	Drum		
2	40	40	Lining (Shoe)	19	19	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: James, Mark Signature:

This Inspection Report was submitted to CVSE on 2025-Jul-18 09:58 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.