



Commercial Vehicle Inspection Report

Decal Number: GJ76297
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21444237

Inspection Result:
PASS

FACILITY:	A.T.R TRUCK REPAIR LTD. / S11270	INSP. TYPE:	Complete	INSP. START:	2025-Jul-30 10:00 AM PST
INSPECTOR:	BAJWA, JUGROOP SINGH / 115050	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Jul-30 11:00 AM PST
WORK ORDER #:		INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	14646338	VIN:	4UGS01318CL011999
PLATE #:	93181K	UNIT/FLEET#:		OWNER/LESSEE NAME:	CARDINAL BOAT MOVERS INC., CARDINAL BOAT MOVERS INC.
LICENCED GVW(kg): 0		BODY STYLE:	Booster Trailer	ADDRESS:	223- 5158 48 AVE Delta, British Columbia V4K5B6, Canada
VEHICLE YEAR:	2012	ODOMETER:			
MAKE:	XL S/A	HUB ODOMETER:			
MODEL:	HEAVY	BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 8A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	38	39	15	9	15	15	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	0	0	Lining (Shoe)	17	17	Drum	420.00	420.00	
Comment:			Comment:		Comment:				

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: BAJWA, JUGROOP SINGH Signature: _____

This Inspection Report was submitted to CVSE on 2025-Jul-30 12:56 PMPST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.