

F12-1



Commercial Vehicle Inspection Report

Decal Number: **GM52688**
 Decal Expiry Date: **2027-Feb-28**
 Inspection Number: **21650522**

Inspection Result:
PASS

FACILITY: ABBY SPRING SERVICE LIMITED / S20051
INSPECTOR: BURTON, JOHN GORDON / 103490
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual

INSP. START: 2026-Feb-02 07:45 AM PST
INSP. COMPLETE: 2026-Feb-02 08:45 AM PST

VEHICLE JUR: British Columbia
PLATE #: PE1778

REGI: 02559386
UNIT/FLEET#: s08

VIN: 1HTMMAAN78H665211
OWNER/LESSEE NAME: MCRAES POWER SWEEPING, mcraes power sweeping ltd
ADDRESS: 28944 downes rd
 Abbotsford, British Columbia
 v4x 1s4, Canada

LICENCED GVW(kg): 12395
VEHICLE YEAR: 2008
MAKE: INTERNATNA
MODEL:

BODY STYLE: Sweeper
ODOMETER: 573414 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) repair worn k-pins
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) repair 2 marker lites
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	30	30	11.9			11.9	✓
2	Clamp	30	Automatic	34	34	13.5	14.3	19.8	19.8	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	45	Lining (Shoe)	12	13	Drum		
2	45	35	Lining (Shoe)	14	17	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**

Inspector: BURTON, JOHN GORDON **Signature:**  **Road Tester:**

This Inspection Report was submitted to CVSE on 2026-Feb-02 10:12 AM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement
 CVSE014
 2/2/2026 10:12:48 AM PST