

F13-1



Commercial Vehicle Inspection Report

Decal Number: GK89548
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21655806

Inspection Result:
PASS

FACILITY: DAWSON TRUCK REPAIRS LTD. / S2467	INSP. TYPE: Complete	INSP. START: 2026-Feb-04 09:07 AM PST
INSPECTOR: MACDONALD, JOSHUA / 201357	INSP. CLASS: Class 2 - Heavy Vehicle with LGVV 5501 kg or more	INSP. COMPLETE: 2026-Feb-05 03:58 PM PST
WORK ORDER #: 4312	INSP. REASON: Semi-annual	

VEHICLE JUR: British Columbia	REGI: 02109175	VIN: 1HTMSAAR59H058475
PLATE #: 82000P	UNIT/FLEET#:	OWNER/LESSEE NAME: ELLIS MOVING & STORAGE, LTD
LICENCED GWV(kg): 23587	BODY STYLE: Van	ADDRESS: 1580 COLUMBIA ST
VEHICLE YEAR: 2009	ODOMETER: 635196 KM	North Vancouver, British Columbia
MAKE: INTERNATNA	HUB ODOMETER:	V7J1A4, Canada
MODEL:	BRAKE TYPE: Air	
	FUEL TYPE:	

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	TOP UP COOLANT, REPAIR OIL LEAKS, REPLACE EXHAUST CLAMP
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACE FRONT BRAKES, REPLACE SECOND AXLE BRAKES
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIR AS REQUIRED
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	WIPER BLADES
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	25	25	10			11	✓
2	Clamp	30L	Automatic	30	30	10	11	13	12	
3	Clamp	30L	Automatic	30	30	17	17	12	8	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	20	20	Lining (Shoe)	21	21	Drum		
2	20	20	Lining (Shoe)	21	21	Drum		
3	50	60	Lining (Shoe)	17	16	Drum		

Inspection Comments:

Has this Vehicle been road tested? Yes Road Test Date: After Inspection Road Tester: MARK

Inspector: MACDONALD, JOSHUA Signature:

This Inspection Report was submitted to CVSE on 2026-Feb-05 03:58 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.