

F13-1



Commercial Vehicle Inspection Report

Decal Number: GK09517
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21405492

Inspection Result:
PASS

FACILITY: MODERN DIESEL TRUCK REPAIR LTD. / S15400
INSPECTOR: RANDHAWA, RAVINDERPAL SINGH / 202804
WORK ORDER #:
VEHICLE JUR: British Columbia
PLATE #: SB8762
LICENCED GVW(kg): 46500
VEHICLE YEAR: 2015
MAKE: INTERNATNA
MODEL:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2025-Jun-26 01:30 PM PDT
INSP. COMPLETE: 2025-Jun-26 02:30 PM PDT
REGI: 13710298
VIN: 1HSDJAPR3FH531364
UNIT/FLEET#: 208
OWNER/LESSEE NAME: LTD., UNIQUE TRUCKING
BODY STYLE: Truck Tractor
ADDRESS: 16268 RIVER RD
ODOMETER: 879157 KM
Richmond, British Columbia
HUB ODOMETER: V6V1L6, Canada
BRAKE TYPE: Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) 2nd r/s max change
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) used steering box replaced
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) front mcase bumper welding
Section 9A - Tires	Repaired (same day) 2nd L/R both 3XL r/s both tyres re-groove
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	30	30
2	Clamp	30L	Automatic	36	37
3	Clamp	30L	Automatic	35	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14			14	✓
5	6	8	8	
9	9	6	5	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	50	65
2	70	69
3	71	69

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	15
Lining (Shoe)	14	14
Lining (Shoe)	14	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: RANDHAWA, RAVINDERPAL SINGH Signature:

This Inspection Report was submitted to CVSE on 2025-Jun-26 02:44 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE014

6/20/2025 2:44:40 PM PDT