



# Commercial Vehicle Inspection Report

Decal Number: GN32155  
 Decal Expiry Date: 2026-Oct-31  
 Inspection Number: 21726951

Inspection Result:  
**PASS**

G06-1

**FACILITY:** HARKO HEAVY DUTY LTD. / S17130  
**INSPECTOR:** KRAJNC, HAYDEN / 202196  
**WORK ORDER #:** METRO MACK DT-23  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Semi-annual  
**INSP. START:** 2026-Apr-09 06:00 AM PDT  
**INSP. COMPLETE:** 2026-Apr-09 07:30 AM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** PA5041  
**LICENCED GVW(kg):** 48000  
**VEHICLE YEAR:** 2012  
**MAKE:** MACK  
**MODEL:**  
**REGI:** 10613730  
**UNIT/FLEET#:** 23-DT  
**BODY STYLE:** Dump Truck  
**ODOMETER:** 873315 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 1M2AX16CXC018053  
**OWNER/LESSEE NAME:** METRO RELOAD, LTD  
**ADDRESS:** 1205 CHEF LOUIS WAY  
 Kamloops, British Columbia  
 V2H1J8, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPAIRED AIR SNUBBER AIRLEAK.
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	REPLACED RH MIRROR LIGHT ASSEMBLY.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	inner R	Outer R	Steering
1	Clamp	24	Automatic	36	36	14			15	✓
2	Clamp	30	Automatic	37	37	11	11	11	11	
3	Clamp	30	Automatic	36	37	13	13	12	13	

Comment: \_\_\_\_\_

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	60	Lining (Shoe)	16	16	Drum		
2	75	83	Lining (Shoe)	14	12	Drum		
3	75	82	Lining (Shoe)	14	12	Drum		

Comment: \_\_\_\_\_

**Inspection Comments:**  
 Has this Vehicle been road tested?  No **Road Test Date:** \_\_\_\_\_ **Road Tester:** \_\_\_\_\_  
**Inspector:** KRAJNC, HAYDEN **Signature:** 

This Inspection Report was submitted to CVSE on 2026-Apr-09 10:02 AMPDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

4/9/2026 10:02:52 AM PDT