



# Commercial Vehicle Inspection Report

Decal Number: GJ75222  
 Decal Expiry Date: 2026-Jun-30  
 Inspection Number: 21374957

Inspection Result: **PASS** *NAS*

**FACILITY:** NIRBHAU TRUCK AND TRAILER REPAIR LTD. / S20286  
**INSPECTOR:** GILL, GURPREET / 300255  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual

**INSP. START:** 2025-Jun-02 09:45 AM PDT  
**INSP. COMPLETE:** 2025-Jun-02 11:01 AM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 14674L  
**LICENCED GVW(kg):** 0  
**VEHICLE YEAR:** 2019  
**MAKE:** UTILITY  
**MODEL:**

**REGI:** 12830364  
**UNIT/FLEET#:** TR046  
**BODY STYLE:** Reefer Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**VIN:** 1UYVS3533K2647912  
**OWNER/LESSEE NAME:** HIGHWAY KING, TRANSPORT LTD.  
**ADDRESS:** 2160 PEARDONVILLE RD  
 Abbotsford, British Columbia  
 V2T 6J8, Canada

Section	Result
Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

**Tire Tread Depth (mm)**

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	44.5	41.3	13	13	13	13	
2	Clamp	30	Automatic	41.3	41.3	8	7	8	10	
3	Clamp	30	Automatic	44.5	47.6	8	7	9	9	

Comment: DUST SHIELDS REMOVED

Comment:

**Air Brake Camshaft Rotation (degrees)**

**Brake Lining/Pad (mm)**

**Rotor Thickness or Drum Inside Diameter (mm)**

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	20	20	Lining (Shoe)	22	22	Drum		
2	20	20	Lining (Shoe)	22	22	Drum		
3	20	20	Lining (Shoe)	22	22	Drum		

Comment:

Comment: DUST SHIELDS REMOVED

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. WHEELS NOT REMOVED

**Inspection Comments:**

Has this Vehicle been road tested?  No  
 Inspector: GILL, GURPREET  
 Road Test Date: \_\_\_\_\_  
 Signature:   
 Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2025-Jun-02 01:24 PMPDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement