



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GK75703
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21476863

Inspection Result:

PASS

FACILITY: VANKO SERVICES LTD / S11470
INSPECTOR: VANDER KOOL, JESSE JACOB / 202950
WORK ORDER #:
VEHICLE JUR: British Columbia
PLATE #: ST2700
LICENCED GVW(kg): 46500
VEHICLE YEAR: 2017
MAKE: WESTERN ST
MODEL:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW
INSP. REASON: Semi-annual
REGI: 12001180
UNIT/FLEET#: 10
BODY STYLE: Truck Tractor
ODOMETER: 99 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
INSP. START: 2025-Aug-28 10:43 AM PDT
INSP. COMPLETE: 2025-Aug-28 12:36 PM PDT
VIN: 5KJJAED11HPJE2442
OWNER/LESSEE NAME: HALLANO FARMS, JOE
ADDRESS: 5385 back enderby rd, 5385 back enderby rd
Enderby, British Columbia
V0E 1B8, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed with Caution	AIR BAGS ARE STARTING TO DRY ROT
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	FIX AIR LEAK AT 3R
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	35	35
2	Clamp	30L	Automatic	37	37
3	Clamp	30L	Automatic	37	38

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	8			8	✓
2	3	3	2	2	
3	10	10	5	2	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	40
2	35	35
3	55	60

Comment:

Brake Lining/Pad (mm)

	Left	Right
Lining/Pad		
Lining (Shoe)	16	16
Lining (Shoe)	17	17
Lining (Shoe)	14	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Left	Right
Rotor/Drum		
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: VANDER KOOL, JESSE JACOB

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-28 12:44 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

8/28/2025 12:44:04 PM PDT