



Commercial Vehicle Inspection Report

Decal Number: GK83137
 Decal Expiry Date: 2026-Sep-30
 Inspection Number: 21512203

Inspection Result:
PASS

FACILITY: CANADIAN SPRING REPAIR LTD. / S20111
INSPECTOR: BHULLAR, PRABHINDER SINGH / 202756
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual

INSP. START: 2025-Sep-25 03:49 PM PDT
INSP. COMPLETE: 2025-Sep-25 05:20 PM PDT

VEHICLE JUR: British Columbia
PLATE #: VL9844
LICENCED GVW(kg): 13581
VEHICLE YEAR: 2000
MAKE: FREIGHTLIN
MODEL:

REGI: 13487451
UNIT/FLEET#:
BODY STYLE: Utility Truck
ODOMETER: 334143 KM
HUB ODOMETER:
BRAKE TYPE: Hydraulic
FUEL TYPE:

VIN: 1FV3GFBC5YHF07421
OWNER/LESSEE NAME: GRAVELLE, ALEXANDRE JASON
ADDRESS: 9428 BARR ST
 Mission, British Columbia
 V2V 7C9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Tire Tread Depth (mm)						Brake Lining/Pad (mm)				Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	13.5			14.3	✓	Pad	12	12	Rotor	35.78	35.81	
2	15.9	15.9	15.9	15.9		Pad	12	12	Rotor	35.49	53.52	
Comment:						Comment:				Comment:		

Inspection Comments:
 Has this Vehicle been road tested? No
 Road Test Date: _____
 Inspector: BHULLAR, PRABHINDER SINGH
 Signature:  Road Tester: _____

This Inspection Report was submitted to CVSE on 2025-Sep-26 06:42 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.