



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GB15541
Decal Expiry Date: 2025-Jul-31
Inspection Number: 21007843

Inspection Result:
PASS

FACILITY:	WESTERN WHEEL TRUCK / S2138	INSR. TYPE:	Complete	INSR. START:	2024-Jul-17 01:00 PM PDT
INSPECTOR:	Boekgaard, Benny / 101307	INSR. CLASS:	Class 3 - Trailer and Semi-Trailer	INSR. COMPLETE:	2024-Jul-17 04:00 PM PDT
WORK ORDER #:	324863	INSR. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	12984452	VIN:	2M513161451101652
PLATE #:	98658U	UNIT/FLEET#:	5314	OWNER/LESSEE NAME:	LUDEMAN, HOLDINGS
LICENCED GVW(kg):	0	BODY STYLE:	High Boy Trailer	ADDRESS:	20170 2ND AVE Langley, British Columbia V2Z0A3, Canada
VEHICLE YEAR:	2005	ODOMETER:			
MAKE:	MANAC	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACE RELAY VALVE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Not Applicable
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable
Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACE RELAY VALVE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Not Applicable
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Stack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	30	30	8	8	8	8	
2	Clamp	30	Automatic	30	30	9	9	8	11	
3	Clamp	30	Automatic	30	30	10	10	8	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	30	30	Lining (Shoe)	19	19	Drum			
2	15	70	Lining (Shoe)	24	13	Drum			
3	30	10	Lining (Shoe)	20	14	Drum			

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: Boekgaard, Benny
Road Test Date:
Signature:
Road Tester:

POSTED
SCANNED

This Inspection Report was submitted to CVSE on 2024-Jul-18 01:24 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations
NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement
CVSE0014
7/18/2024 1:25:00 PM PDT

Ludeman Trucking Ltd.
 20170 - 2nd Ave
 Langley , BC V2Z 0A3 Canada
 Phone: 604-525-8826

Work Orders Completed: Grouped by Equipment Number

Equip Num From: 5314 To: 5314 AND Sort By: Equip Number

Equip Num 5314

Desc: Highboy

Work Order ID	Ref Num	Requested By	Requested Dt	Complete By Date	Completed Date	Completed Mi/Km	Completed Hours	Description(s)	Total
17			2023-11-21		2023-11-23			rebuild top air bag mount Replace rear light bar Service & Lube Replace RC airbag	\$1,532.95
44			2024-01-15		2024-01-15			Brake job LC - Drum 80/120	\$683.03
198			2024-03-22		2024-04-02			Service & Lube BRAKE JOB LF DRUM 80/120 ROCK Q' REPAIR SPIDER. DUST PLATE AND NEW OIL SEAL REPAIR TO SLIDER AND CHANGE 1 SLIDER PAD REPAIR CROSSMEMBERS ON RIGHT FRONT	\$2,877.53
237			2024-05-17		2024-05-17			Brake job RF drum 50/120 q shoes re/re syder & dust plates re/re lights & wiring Oil Leak RF	\$882.53
281			2024-07-22		2024-07-22			Commercial Vehicle inspection	\$157.50
371			2024-10-10		2024-10-10			Service & Lube check frame for rust	\$399.00
475			2025-02-25		2025-02-25			Service & Lube repair rotten crossmembers front axle relay valave changed re/re airlines	\$2,394.00
Work Order Totals for Equipment Number 5314									\$8,926.54

Ludeman Trucking Ltd.
20170 - 2nd Ave
Langley , BC V2Z 0A3 Canada
Phone: 604-525-8826

Work Orders Completed: Grouped by Equipment Number

Equip Num From: 5314 To: 5314 AND Sort By: Equip Number

Work Order Totals for This Report

\$8,926.54