



Commercial Vehicle Inspection Report

Decal Number: GK81406
 Decal Expiry Date: 2026-Aug-31
 Inspection Number: 21470592

611
 Inspection Result:
PASS

FACILITY: ARSARA DIESEL TRUCK / S5708 **INSP. TYPE:** Complete **INSP. START:** 2025-Aug-22 09:08 AM PDT
INSPECTOR: BAL, AMANDIP / 300258 **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer **INSP. COMPLETE:** 2025-Aug-22 08:18 PM PDT
WORK ORDER #: **INSP. REASON:** Annual

VEHICLE JUR: British Columbia **REGI:** 11110367 **VIN:** 2LDS5330BG051843
PLATE #: 56950J **UNIT/FLEET#:** 704A **OWNER/LESSEE NAME:** GOLD LEAF CARRIERS INC.
LICENCED GVW(kg): 999999 **BODY STYLE:** Flat Deck Trailer **ADDRESS:** PO BOX 34116
VEHICLE YEAR: 2011 **ODOMETER:** **Surrey, British Columbia**
MAKE: LODE KING **HUB ODOMETER:** **V3S 8C4, Canada**
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) 3XL BOTH SIDE AIR BAG REPLACED
Section 3A - Air Brakes	Repaired (same day) 3XL LEFT SIDE BRAKE DRUM REPLACED 1XL LEFT SIDE 3XL LEFT SIDE MAXI REPLACED 2XL RIGHT SIDE 3XL BOTH SIDE SLACK REPLACED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) 3XL RIGHT SIDE BOTH TIRE REPLACED
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31	33	11	11	10	9	
2	Clamp	30	Automatic	32	35	15	14	9	10	
3	Clamp	30	Automatic	35	36	9	5	3	4	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	46	46	Lining (Shoe)	17	17	Drum		
2	48	45	Lining (Shoe)	16	17	Drum		
3	96	51	Lining (Shoe)	12	16	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: BAL, AMANDIP **Signature:**

This Inspection Report was submitted to CVSE on 2025-Aug-22 08:19 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

8/22/2025 8:19:54 PM PDT