



Commercial Vehicle Inspection Report

Decal Number: **GM72257**
 Decal Expiry Date: **2026-Aug-31**
 Inspection Number: **21665613**

Inspection Result: **PASS**

FACILITY: ARSARA DIESEL TRUCK / S5708 **INSP. TYPE:** Complete **INSP. START:** 2026-Feb-14 09:04 AM PST
INSPECTOR: BAL. AMANDIP / 300258 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVV 5501 kg or more **INSP. COMPLETE:** 2026-Feb-14 06:50 PM PST
WORK ORDER #: **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 13808621 **VIN:** 3HSDZAPR8NN342271
PLATE #: 97142P **UNIT/FLEET#:** 9013 **OWNER/LESSEE NAME:** GOLD LEAF CARRIERS INC.
LICENCED GVW(kg): 47000 **BODY STYLE:** Truck Tractor **ADDRESS:** 18788 55A AVE
VEHICLE YEAR: 2022 **ODOMETER:** 1292608 KM Surrey, British Columbia
MAKE: INTERNATNA **HUB ODOMETER:** V3S 4N7, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) 2XL RIGHT SIDE BRAKE DRUM REPLACED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	32	31
2	Clamp	30L	Automatic	34	33
3	Clamp	30L	Automatic	30	32

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8			10	✓
11	13	12	12	
12	12	12	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	51	50
2	63	98
3	48	48

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	15	12
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? **No** Road Test Date: Road Tester:
 Inspector: **BAL. AMANDIP** Signature:

This Inspection Report was submitted to CVSE on 2026-Feb-14 06:51 PMPST
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSED014

2/14/2026 6:51:29 PM PST