



Commercial Vehicle Inspection Report

Decal Number: GM44590
 Decal Expiry Date: 2026-Aug-31
 Inspection Number: 21667778

H06-11
 Inspection Result:
PASS

FACILITY: WALKER HEAVY DUTY LTD. / S7256
INSPECTOR: VAN DER HOEK, PETER DANIEL / 201883
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual

INSP. START: 2026-Feb-18 08:00 AM PST
INSP. COMPLETE: 2026-Feb-18 10:00 AM PST

VEHICLE JUR: British Columbia
PLATE #: 51893D
LICENCED GWV(kg): 999999
VEHICLE YEAR: 2015
MAKE: NAHANNI
MODEL:

REGI: 11235122
UNIT/FLEET#: T03
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2N9EDB2E7FL055609
OWNER/LESSEE NAME: J&R EXCAVATION AND DEMOLITION LTD.
ADDRESS: 7782 PROGRESS WAY
 Delta, British Columbia
 V4G1A4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A- Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A- Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				
						Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	36	15	16	15	16	
2	Clamp	30	Automatic	35	34	14	14	13	13	
Comment:						Comment:				

Axles	Left	Right	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
			Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	35	40	Lining (Shoe)		19	18	Drum		
2	40	45	Lining (Shoe)		19	19	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:
 Has this Vehicle been road tested? No Yes
Inspector: VAN DER HOEK, PETER DANIEL
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-18 11:58 AMPST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.