



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM08182
Decal Expiry Date: 2028-Jun-30
Inspection Number: 21582281

Inspection Result:

PASS

FACILITY: NIXON BROS. TRUCK REPAIR LTD. / 818280
INSPECTOR: Mattars, Trevor William / 105817
WORK ORDER #: 81827
INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSR. REASON: Semi-annual
INSR. START: 2025-Dec-04 08:45 AM PST
INSR. COMPLETE: 2025-Dec-04 10:10 AM PST

VEHICLE JUR: British Columbia
PLATE #: A1B8E8
LICENCED GVW(kg): 48500
VEHICLE YEAR: 2008
MAKE: STERLING
MODEL:
REGI: 03138382
UNIT/FLEET#:
BODY STYLE: Truck Tractor
ODOMETER: 473313 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2FWJAZCK38AV43851
OWNER/LESSEE NAME: MALAHAT HOTSHOT LTD.,
ADDRESS: 2325 KEDGE ANCHOR RD
North Saanich, British Columbia
V6L5J1, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Passed
Section 2 - Suspension Passed
Section 3 - Brake System Passed
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Passed
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	20	Automatic	28	31	10.3			12.7	✓
2	Clamp	30L	Automatic	33	32	5.8	7.1	5.8	6.4	
3	Clamp	30L	Automatic	28	33	7.1	6.4	4.8	6.4	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	
			Lining/Pad			Rotor/Drum	Left Right
1	45	45	Lining (Shoe)	17	17	Drum	
2	33	34	Lining (Shoe)	19	19	Drum	
3	35	35	Lining (Shoe)	19	19	Drum	

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments: IN COMPLIANCE AT TIME OF INSPECTION

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: Mattars, Trevor William Signature: _____

This Inspection Report was submitted to CVSE on 2025-Dec-04 10:17 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the St. Manager, NSOVP at the Commercial Vehicle Safety Enforcement

CVSE014

1/20/2028 10:53:49 AM PST