



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM38526
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21631260

Inspection Result:

PASS

FACILITY:	NIXON BROS. TRUCK REPAIR LTD. / S16280	INSP. TYPE:	Complete	INSP. START:	2026-Jan-15 08:00 AM PST
INSPECTOR:	METTERS, DEVON / 301613	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jan-15 02:27 PM PST
WORK ORDER #:	82001	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	14432805	VIN:	1M1AA18Y2YW133420
PLATE #:	A1M8C6	UNIT/FLEET#:		OWNER/LESSEE NAME:	MALAHAT HOTSHOT LTD.,
LICENCED GVW(kg):	83500	BODY STYLE:	Truck Tractor	ADDRESS:	2325 KEDGE ANCHOR RD
VEHICLE YEAR:	2000	ODOMETER:	206391 KM		North Saanich, British Columbia
MAKE:	MACK	HUB ODOMETER:			V8L5J1, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	Secure alternator to engine
Section 2 - Suspension	Repaired (same day)	Tighten #3 Left U bolts
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	Replace #3 Right spring brake chamber
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day)	Repair speedo backlight
Section 6 - Lamps	Repaired (same day)	Replace right side turn signal, replace burnt out cab id light Right of center, replace license plate light.
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	Repair driver side center fuel tank strap, replace driver side front most fuel tank strap, Replace windshield washer pump.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	19.1	19.1	7.9			7.9	✓
2	Clamp	30	Automatic	38.1	44.5	14.3	11.1	5.6	5.6	
3	Clamp	30	Automatic	31.8	38.1	6.4	6.4	7.9	7.1	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	58	51
2	30	29
3	55	38

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	19	19
Lining (Shoe)	16	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: METTERS, DEVON

Signature:

[Signature]

This Inspection Report was submitted to CVSE on 2026-Jan-15 02:28 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE014

1/15/2026 2:28:59 PM PST