

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

GK65815 2026-Mar-31 21512583

Inspection Result: Ho

CILITY: SPECTOR:

SOS REPAIRS / S5681

SLATER, GARY ROBERT / 107516

INSP. TYPE: INSP. CLASS:

Complete

INSP. START:

2025-Sep-27 08:00 AM PDT

DRK ORDER #:

INSP. REASON:

Class 2 - Heavy Vehicle with LGVW 5501 kg or more

INSP. COMPLETE:

2025-Sep-27 10:00 AM PDT

HICLE JUR: ATE #:

British Columbia

SL7094

REGI: UNIT/FLEET#: 10232073

VIN:

1XPWDP0X6CD140117

Mission, British Columbia

V2V 3Z2, Canada

CENCED GVW(kg): 58000 HICLE YEAR: AKE:

shicle Identification (VIN)

ection 1 - Power Train

ection 2 - Suspension

DDFL:

2012 PETERBILT BODY STYLE: ODOMETER:

Truck Tractor 350103 KM

Semi-annual

OWNER/LESSEE NAME: ADDRESS:

Transwood Timber, LTD. 7765 Horne ST, 7765 Horne ST

HUB ODOMETER:

BRAKE TYPE:

Air

Passed

Passed Passed

ection 3 - Brake System ection 3A - Air Brakes ection 3H - Hydraulic Brakes ection 4 - Steering

ection 5 - Instruments and Auxiliary

quipment ection 6 - Lamps ection 7 - Electrical System ection 8 - Frame and Body ection 9A - Tires ection 9B - Wheels ection 10 - Coupling Devices

ection 11 - Other Vehicle Components

FUEL TYPE:

Passed Passed Not Applicable

Passed Passed Passed Passed Passed Passed

Passed Passed Not Applicable

· Brake Chamber	Type, Size	and Push	Rod	Stroke	(mm)
	., 100, 0120	una i uon	Nou	OLIONE	(, , , , , , ,

Brake Ghamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	28	27	14			13	~
2	Clamp	30	Automatic	33	32	3	4	4	4	
3	Clamp	30	Automatic	34	32	3	3	4	3	
omment:						Comment:				

· Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	40	40	Lining (Shoe)	18	18	Drum			
2	80	85	Lining (Shoe)	14	14	Drum			
3	80	85	Lining (Shoe)	14	14	Drum			
omment:			Comment:				mment: Air Brake Camshaft Rotation performed. Rockness or Drum Diameter not measured.		

spection Comments:

spector:

s this Vehicle been road tested? SLATER, GARY ROBERT Road Test Date:

Signature:

s Inspection Report was submitted to CVSE on 2025-Sep-27 12:18 PM PDT

No

3 Inspector's signature above is certification that this wehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

SE0014