

# Commercial Vehicle Inspection Report

Decal Number: **GK65817**  
 Decal Expiry Date: **2026-Sep-30**  
 Inspection Number: **21512655**

Inspection Result:  
**PASS** *409*

<b>CILITY:</b>	SOS REPAIRS / S5681	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2025-Sep-27 10:30 AM PDT
<b>SPECTOR:</b>	SLATER, GARY ROBERT / 107516	<b>INSP. CLASS:</b>	Class 3 - Trailer and Semi-Trailer	<b>INSP. COMPLETE:</b>	2025-Sep-27 11:45 AM PDT
<b>CRK ORDER #:</b>		<b>INSP. REASON:</b>	Annual		

  

<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	10853898	<b>VIN:</b>	2P9LB6026EL096203
<b>ATE #:</b>	56811K	<b>UNIT/FLEET#:</b>	725259	<b>OWNER/LESSEE NAME:</b>	Transwood Timber, LTD.
<b>PERMITTED GVW(kg):</b>	999999	<b>BODY STYLE:</b>	Lowbed Trailer	<b>ADDRESS:</b>	7765 Home ST, 7765 Home ST
<b>VEHICLE YEAR:</b>	2014	<b>ODOMETER:</b>			Mission, British Columbia
<b>MAKE:</b>	PACESSETTER	<b>HUB ODOMETER:</b>			V2V 3Z2, Canada
<b>MODEL:</b>	60 TO	<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed with Caution #1 suspension
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	38	14	14	14	14	
2	Clamp	30	Automatic	40	41	14	14	14	14	
Comment:						Comment:				

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Left	Right	Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	85	90	Lining (Shoe)		12	12	Drum		
2	35	35	Lining (Shoe)		20	20	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.				

**Inspection Comments:**  
 Is this Vehicle been road tested? ☐ No **Road Test Date:**                      **Road Tester:**                       
**Inspector:** SLATER, GARY ROBERT **Signature:** *Gary Slater*

This Inspection Report was submitted to CVSE on 2025-Sep-27 12:53 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**PLEASE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**

Personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCAVP at the Commercial Vehicle Safety Enforcement.

SED014

7/2025 12:54:09 PM PDT