



Commercial Vehicle Inspection Report

Decal Number: GK23749
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21421945

Inspection Result:
PASS

FACILITY:	BANSAL & SONS DIESEL / S0446	INSP. TYPE:	Complete	INSP. START:	2025-Jul-09 02:00 PM PDT
INSPECTOR:	Bansal, Manraj singh / 114542	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jul-10 07:00 PM PDT
WORK ORDER #:	10293	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	10874359	VIN:	4V4NC9EH4EN159375
PLATE #:	48276P	UNIT/FLEET#:		OWNER/LESSEE NAME:	TRANS CANADA MOVERS INC., TRANS CANADA
LICENCED GVW(kg):	40000	BODY STYLE:	Truck Tractor	ADDRESS:	#8 - 1080 CLIVEDEN AVENUE
VEHICLE YEAR:	2014	ODOMETER:	1299495 KM		Delta, British Columbia
MAKE:	VOLVO	HUB ODOMETER:			V3M6G6, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	REPLACED BOTH ENGINE BELTS, REPLACED INTER AXLE PASSENGER SIDE WHEEL SEAL
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	REPLACED WINDSHIELD WASHER RESERVOIR CAP
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	36	36	12			10	✓
2	Clamp	30	Automatic	35	35	5	8	10	10	
3	Clamp	30	Automatic	35	35	9	9	8	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	40	43	Lining/Pad			Rotor/Drum		
2	29	41	Lining (Shoe)	14	14	Drum		
3	34	39	Lining (Shoe)	18	18	Drum		
			Lining (Shoe)	16	16	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Bansal, Manraj singh
Road Test Date: 
Signature: _____
Road Tester: _____

This Inspection Report was submitted to CVSE on 2025-Jul-10 07:04 PMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSED014

7/10/2025 7:04:18 PM PDT