

Commercial Vehicle **Inspection Report**

Decal Number: **Decal Expiry Date:** Inspection Number: GK64599 2026-Sep-30 21493328

Inspection Result:

FACILITY: BANSAL & SONS DIESEL / S0446 INSP. TYPE: Complete INSP. START: 2025-Sep-09 10:25 AM PDT INSPECTOR: DEOL, SUKHMAN-SINGH / 300572 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2025-Sep-11 11:48 AM PDT 5501 kg or more WORK ORDER #: 10592 INSP. REASON: Annual VEHICLE JUR: British Columbia REGI: 10608700 VÍN: 1FVACXDU8CDBU3252 PLATE #: 53521P UNIT/FLEET#: OWNER/LESSEE NAME: TRANS CANADA MOVERS INC., TRANS CANADA LICENCED GVW(kg): 14500 **BODY STYLE:** Van ADDRESS: #8 - 1080 CLIVEDEN AVENUE VEHICLE YEAR: 2012 ODOMETER: 415362 KM Delta, British Columbia MAKE: **FREIGHTLIN** HUB ODOMETER: V3M6G6, Canada MODEL: BRAKE TYPE: Hydraulic **FUEL TYPE:** Vehicle Identification (VIN) Passed Section 1 - Power Train Passed Section 2 - Suspension Passed Section 3 - Brake System Repaired (same day) REPLACED REAR BRAKE PADS AND ROTORS Section 3H - Hydraulic Brakes Passed Section 4 - Steering Repaired (same day) REPLACED STEERING SHAFT Section 5 - Instruments and Auxiliary Passed Equipment Section 6 - Lamps Repaired (same day) REPLACED D/S REAR MIDDLE BOX MARKER LIGHT AND REPLACED REVERSE ALARM Section 7 - Electrical System Passed Section 8 - Frame and Body Repaired (same day) REPLACED WIPER BLADES Section 9A- Tires Passed Section 9B - Wheels Passed Section 10 - Coupling Devices Not Applicable Section 11 - Other Vehicle Components Not Applicable Tire Tread Depth (mm) Brake Lining/Pad (mm) Rotor Thickness or Drum Inside Diameter (mm) Axles Outer L Inner L Inner R Outer R Lining/Pad Steering Left Right Rotor/Drum Left Right 19 🗸 19 Pad 14 14 Rotor 38.71 38.84 2 11 11 Pad 16 16 Rotor 0.00 0.00

Inspection Comments:

Comment:

Has this Vehicle been road tested? Inspector: DEOL, SUKHMAN-SINGH Road Test Date: Signature:

Comment: REPLACED REAR BRAKE PADS

Road Tester:

Comment: REPLACED REAR BRAKE ROTORS

This Inspection Report was submitted to CVSE on 2025-Sep-11 11:48 AMPDT

No

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.