



Commercial Vehicle Inspection Report

Decal Number: GH78740
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21268051

Inspection Result:

PASS

FACILITY: KC TRUCK AND TRAILER REPAIR LTD. / S17090
INSPECTOR: SIDHU, PAWANPREET / 201923
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Mar-12 12:00 PM PDT
INSP. COMPLETE: 2025-Mar-12 01:12 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 79367K
LICENCED GVW(kg): 0
VEHICLE YEAR: 1998
MAKE: HYUNDAI
MODEL:
REGI: 13399831
UNIT/FLEET#: 0125
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 076014
OWNER/LESSEE NAME: .. TRANS CANADA MOVERS INC.
ADDRESS: 8-1080 CLVEDEN AVE
Delta, British Columbia
V3M 6G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) roof leakage fixed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	34	34	13.5	13.5	7.9	7.1	
2	Clamp	30	Automatic	34	34	8.7	9.5	15.1	15.9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right
1	45	42
2	68	70

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	12	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SIDHU, PAWANPREET

Signature:

This Inspection Report was submitted to CVSE on 2025-Mar-12 02:14 PM PDT

The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement

CVSE0014

3/12/2025 2:14:06 PM PDT