

Commercial Vehicle Inspection Report

 Decal Number: **GM33967**
 Decal Expiry Date: **2026-Aug-31**
 Inspection Number: **21668359**
H#3-1

 Inspection Result:

PASS

FACILITY:	GEMM DIESEL LTD. / S3195	INSP. TYPE:	Complete	INSP. START:	2026-Feb-18 02:18 PM PST
INSPECTOR:	Kraft, Christopher Michael / 111916	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Feb-18 04:19 PM PST
WORK ORDER #:	W80225	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	03732142	VIN:	1NKDL40X37R991972
PLATE #:	WV6029	UNIT/FLEET#:		OWNER/LESSEE NAME:	LTD, NORTHWAY ROCKS
PERMITTED GVW(kg):	60100	BODY STYLE:	Dump Truck	ADDRESS:	PO BOX 24, 1009 LARCH AVE
VEHICLE YEAR:	2007	ODOMETER:	872730 KM		Sicamous, British Columbia
MAKE:	KENWORTH	HUB ODOMETER:			VOE2V0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed with Caution	WALKING BEAM BUSHING CRACKED BUT NO PLAY , REPLACED REAR SPRING PINS AND BUSHINGS ON STEER AXLE
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACED R2 SLACK ADJUSTER , INSTALL NEW CLEVIS ON R2 , REPLACED ON R3 S-CAM AND BUSHINGS
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxillary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIRED BECON LIGHT
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	34	33	15			15	✓
2	Clamp	30	Automatic	36	38	12	11	11	11	
3	Clamp	30	Automatic	38	38	8	9	9	9	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	38	Lining (Shoe)	16	16	Drum		
2	60	65	Lining (Shoe)	13	12	Drum		
3	98	90	Lining (Shoe)	12	12	Drum		

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____

Inspector: Kraft, Christopher Michael **Signature:** 

This Inspection Report was submitted to CVSE on 2026-Feb-18 04:23 PMPST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.