



Commercial Vehicle Inspection Report

Decal Number: GC32260
 Decal Expiry Date: 2026-Apr-30
 Inspection Number: 21518909

JUS-2
 Inspection Result:
PASS

AGENCY: MILLER CAPILANO / S6738 **INSP. TYPE:** Complete **INSP. START:** 2025-Sep-27 02:00 PM PDT
INSPECTOR: Mazzotti, Phillip / 301193 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2025-Oct-02 02:23 PM PDT
WORK ORDER #: **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 12840960 **VIN:** 1NKDX4EX9KJ956230
LATE #: NB1584 **UNIT/FLEET#:** 52 **OWNER/LESSEE NAME:** J.R Transport LTD, J.R Transport LTD
PERMITTED GVW(kg): 59000 **BODY STYLE:** Truck Tractor **ADDRESS:** PO box 2359
VEHICLE YEAR: 2019 **ODOMETER:** 555295 KM Squamish, British Columbia
MAKE: KENWORTH **HUB ODOMETER:** V8B0B6, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) exhaust clamps at turbo and flex pipe replaced
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) main wiring harness for all markers replaced
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	40	40	15			15	✓
2	Clamp	30	Automatic	40	40	21	21	21	21	
3	Clamp	30	Automatic	40	40	21	21	21	21	
4	Clamp	30	Automatic	40	40	21	21	21	21	

Comment: all new drives week before

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	45	Lining (Shoe)	19	19	Drum		
2	68	60	Lining (Shoe)	16	18	Drum		
3	55	58	Lining (Shoe)	17	17	Drum		
4	75	75	Lining (Shoe)	15	16	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? Yes No
 Inspector: Mazzotti, Phillip

Road Test Date: _____ Road Tester: _____
 Signature: 

This Inspection Report was submitted to CVSE on 2025-Oct-02 02:25 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.



Commercial Vehicle Inspection Report

Decal Number: **GM20165**
 Decal Expiry Date: **2026-Sep-30**
 Inspection Number: **21708224**

Inspection Result:
PASS

305 2

FACILITY: TNM Service and Repairs / S20529 **INSP. TYPE:** Complete **INSP. START:** 2026-Mar-18 08:00 AM EDT
INSPECTOR: Mazzotti, Phillip / 301193 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2026-Mar-25 05:57 AM EDT
WORK ORDER #: **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 12840960 **VIN:** 1NKDX4EX9KJ958230
PLATE #: XE5680 **UNIT/FLEET#:** 52 **OWNER/LESSEE NAME:** JR Transport LTD, JR Transport LTD
LICENCED GVW(kg): 59000 **BODY STYLE:** Truck Tractor **ADDRESS:** 38610 Loggers Lane
VEHICLE YEAR: 2019 **ODOMETER:** 581075 KM Squamish, British Columbia
MAKE: KENWORTH **HUB ODOMETER:** V8B 0B6, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed with Caution High cam rotation, drums to be changed next brake job
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) Left side drag link replaced
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Right Side bumper marker fixed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	40	40	12			12	✓
2	Clamp	30L	Automatic	40	40	15	18	16	17	
3	Clamp	30L	Automatic	40	40	16	19	17	19	
4	Clamp	30L	Automatic	40	40	15	14	15	15	
Comment: change drums next brake job						Comment:				

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement



Commercial Vehicle Inspection Report

Decal Number: GM20165
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21708224

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	80	80	Lining (Shoe)	16	16	Drum		
2	90	85	Lining (Shoe)	16	15	Drum		
3	90	100	Lining (Shoe)	15	16	Drum		
4	100	100	Lining (Shoe)	15	15	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: Mazzotti, Phillip

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026 Mar 25 08:59 AM EDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

3/25/2026 8:59:55 AM EDT