



Commercial Vehicle Inspection Report

Decal Number: GM20168
 Decal Expiry Date: 2026-Sep-30
 Inspection Number: 21708304

Inspection Result:
PASS

JOS-3

FACILITY: TNM Service and Repairs / S20529 **INSP. TYPE:** Complete **INSP. START:** 2026-Mar-24 05:00 AM EDT
INSPECTOR: Mazzotti, Phillip / 301193 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2026-Mar-25 06:23 AM EDT
WORK ORDER #: **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 11323263 **VIN:** 1XKDP4EX1FR976677
PLATE #: XE5679 **UNIT/FLEET#:** 50 **OWNER/LESSEE NAME:** JR Transport LTD, JR TRansport LTD
LICENCED GVW(kg): 59000 **BODY STYLE:** Logging Truck **ADDRESS:** 38610 Loggers Lane
VEHICLE YEAR: 2015 **ODOMETER:** 882179 KM **Squamish, British Columbia**
MAKE: KENWORTH **HUB ODOMETER:** **V8B 0B6, Canada**
MODEL: **BRAKE TYPE:** Air **FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) Loose V clamp at turbo
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	40	40
2	Clamp	30L	Automatic	40	40
3	Clamp	30L	Automatic	40	40
4	Clamp	30L	Automatic	40	40

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
18			18	✓
17	16	18	18	
13	13	13	14	
15	15	14	16	

Comment:



Commercial Vehicle Inspection Report

Decal Number: GM20168
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21708304

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	20	Lining (Shoe)	15	15	Drum		
2	65	60	Lining (Shoe)	17	13	Drum		
3	75	75	Lining (Shoe)	17	14	Drum		
4	40	80	Lining (Shoe)	16	13	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: Mazzotti, Phillip

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-25 09:25 AM EDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/V/P at the Commercial Vehicle Safety Enforcement.

CVSE0014

3/25/2026 9:26:14 AM EDT