



Commercial Vehicle Inspection Report

Decal Number: GC32261
 Decal Expiry Date: 2026-May-31
 Inspection Number: 21555423

Inspection Result:
PASS

ITY: MILLER CAPILANO / S6738 INSP. TYPE: Complete INSP. START: 2025-Nov-03 02:00 PM PST
 CTOR: Mazzotti, Phillip / 301193 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2025-Nov-04 08:56 AM PST
 ORDER #: INSP. REASON: Semi-annual

LE JUR: British Columbia REGI: 11323263 VIN: 1XKDP4EX1FR976677
 #: KR4394 UNIT/FLEET#: 50 OWNER/LESSEE NAME: JR Transport LTD, JR Transport LTD
 CED GVW(kg): 59000 BODY STYLE: Logging Truck ADDRESS: po Box 2359
 LE YEAR: 2015 ODOMETER: 865643 KM Squamish, British Columbia
 : KENWORTH HUB ODOMETER: V8B 0B6, Canada
 :L: BRAKE TYPE: Air
 FUEL TYPE:

Vehicle Identification (VIN)	Passed
on 1 - Power Train	Passed
on 2 - Suspension	Passed
on 3 - Brake System	Repaired (same day) Left steer axle brakes changed
on 3A - Air Brakes	Passed
on 3H - Hydraulic Brakes	Not Applicable
on 4 - Steering	Passed
on 5 - Instruments and Auxiliary Equipment	Passed
on 6 - Lamps	Passed
on 7 - Electrical System	Passed
on 8 - Frame and Body	Repaired (same day) Cross-member under cab changed
on 9A - Tires	Passed
on 9B - Wheels	Passed
on 10 - Coupling Devices	Passed
on 11 - Other Vehicle Components	Passed

Axle	Chamber Type	Size	Slack Adj.	Rod Stroke (mm)		Tire Tread Depth (mm)				Steering
				Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Not Applicable	40	40	12.7			12.7	✓
2	Clamp	30L	Not Applicable	40	40	18.3	18.3	18.3	18.3	
3	Clamp	30L	Not Applicable	40	40	19.1	19.1	19.1	19.1	
4	Clamp	30L	Not Applicable	40	40	19.1	19.1	19.1	19.1	

Comment: higher cam rotations should get new drums for nex brake job and inspect cam bushings

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	60	Lining (Shoe)	20	18	Drum		
2	95	82	Lining (Shoe)	17	15	Drum		
3	87	90	Lining (Shoe)	17	15	Drum		
4	80	100	Lining (Shoe)	17	16	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No
 Inspector: Mazzotti, Phillip

Road Test Date:
 Signature:



Road Tester:

This inspection Report was submitted to CVSE on 2025-Nov-04 09:01 AMPST
 Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.