



Commercial Vehicle Inspection Report

Decal Number: GM20166
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21710343

305-4
Inspection Result:
PASS

FACILITY: TNM Service and Repairs / S20529 **INSP. TYPE:** Complete **INSP. START:** 2026-Mar-25 05:30 AM EDT
INSPECTOR: KILBY, MICHAEL ODIN KIRKDALE / 301190 **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer **INSP. COMPLETE:** 2026-Mar-25 02:20 PM EDT
WORK ORDER #: **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 10272895 **VIN:** 2P9JG3AT0B1074090
PLATE #: 59803K **UNIT/FLEET#:** **OWNER/LESSEE NAME:** J.R. TRANSPORT LTD., J.R. TRANSPORT LTD.
LICENCED GWV(kg): 999999 **BODY STYLE:** LOGGING TRAILER **ADDRESS:** 38810 LOGGERS LANE
VEHICLE YEAR: 2011 **ODOMETER:** Squamish, British Columbia
MAKE: FREFLYT **HUB ODOMETER:** V8B 0B6, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) replace brake lining on rear axle right wheel.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) replace hold down spring on compensator latch
Section 6 - Lamps	Repaired (same day) repair wire for marker light operation
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) grind out and weld up crack behind bunk on left hand side of barrel
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	21	14	12	15	
2	Clamp	30	Automatic	40	40	15	18	13	14	
3	Clamp	30	Automatic	35	50	18	18	18	18	

Comment: the rear right brake rotation measurement was from before the lining was replaced.

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	70	60	Lining (Shoe)	17	17	Drum		
2	50	30	Lining (Shoe)	18	18	Drum		
3	25	115	Lining (Shoe)	19	13	Drum		

Comment:

Comment: lining on rear right brake was replaced with brand new lining.

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**  **Road Tester:**
Inspector: KILBY, MICHAEL ODIN KIRKDALE **Signature:**

This Inspection Report was submitted to CVSE on 2026-Mar-26 01:18 PM EDT
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSED014
3/26/2026 1:18:39 PM EDT