



# Commercial Vehicle Inspection Report

Decal Number: GM20153  
 Decal Expiry Date: 2028-Jun-30  
 Inspection Number: 21592391

JOS-4  
 Inspection Result:  
**PASS**

**FACILITY:** TNM Service and Repairs / S20529 **INSP. TYPE:** Complete **INSP. START:** 2025-Dec-01 05:00 AM EST  
**INSPECTOR:** Mazzotti, Phillip / 301193 **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer **INSP. COMPLETE:** 2025-Dec-04 08:00 AM EST  
**WORK ORDER #:** 55B **INSP. REASON:** Semi-annual

**VEHICLE JUR:** British Columbia **REGI:** 10272895 **VIN:** 2P9JG3AT0B1074090  
**PLATE #:** 59803K **UNIT/FLEET#:** 55B **OWNER/LESSEE NAME:** JR Transport LTD, JR Transport LTD  
**LICENCED GVW(kg):** 999999 **BODY STYLE:** LOGGING TRAILER **ADDRESS:** 38810 Loggers Lane  
**VEHICLE YEAR:** 2011 **ODOMETER:** **Squamish, British Columbia**  
**MAKE:** FREFLYT **HUB ODOMETER:** V8B 0B6, Canada  
**MODEL:** **BRAKE TYPE:** Air  
**FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) #2 axle right side slack s-cam and bushings #2 axle left side slack washers/snap ring #3 axle left side lining and slack washers #3 axle right side slack adjuster and service pot
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) left side stake ext. bushing replaced main stake bushing replaced bolster cracks welded up
Section 9A - Tires	Repaired (same day) rear axle tires replaced
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	13.5	14.3	13.5	15.1	
2	Clamp	30	Automatic	40	40	14.3	19.1	12.7	15.9	
3	Clamp	30	Automatic	40	40	10.3	7.9	7.9	8.7	

Comment: right rear is a caution, drum/lining and cam bushings all pass

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	80	Lining (Shoe)	18	18	Drum		
2	45	55	Lining (Shoe)	19	17	Drum		
3	85	105	Lining (Shoe)	15	15	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Inspection Comments:**  
 Has this Vehicle been road tested?  No **Road Test Date:**  **Road Tester:**  
**Inspector:** Mazzotti, Phillip **Signature:**

This Inspection Report was submitted to CVSE on 2025-Dec-04 11:26 AM EST  
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.