



# Commercial Vehicle Inspection Report

Decal Number: GM20167  
 Decal Expiry Date: 2026-Sep-30  
 Inspection Number: 21710422

Inspection Result:  
**PASS**

FACILITY: TNM Service and Repairs / S20529 INSP. TYPE: Complete INSP. START: 2026-Mar-25 08:41 AM EDT  
 INSPECTOR: KILBY, MICHAEL ODIN KIRKDALE / 301190 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Mar-26 09:42 AM EDT  
 WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 10422033 VIN: 2P9JG3ATXC1074101  
 PLATE #: 93001J UNIT/FLEET#: OWNER/LESSEE NAME: J.R. TRANSPORT LTD., J.R. TRANSPORT LTD.  
 LICENCED GVW(kg): 999999 BODY STYLE: LOGGING TRAILER ADDRESS: PO BOX 2359  
 VEHICLE YEAR: 2012 ODOMETER: Squamish, British Columbia  
 MAKE: FREFLYT HUB ODOMETER: V8B 0B6, Canada  
 MODEL: JG3AT BRAKE TYPE: Air FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) repair leaking glad hand rubber
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) repair marker light wiring on rear left side of body by bunk
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) grind out and weld up crack on left hand side of barrel behind bunk
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

**Tire Tread Depth (mm)**

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	50	50	14	13	12	14	
2	Clamp	30	Automatic	38	38	14	16	11	13	
3	Clamp	30	Automatic	50	50	18	17	17	18	

Comment:

Comment:

**Air Brake Camshaft Rotation (degrees)**

**Brake Lining/Pad (mm)**

**Rotor Thickness or Drum Inside Diameter (mm)**

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	75	75	Lining (Shoe)	19	19	Drum		
2	30	45	Lining (Shoe)	19	19	Drum		
3	90	45	Lining (Shoe)	16	19	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Inspection Comments:**

Has this Vehicle been road tested? No Road Test Date:  Road Tester:  
 Inspector: KILBY, MICHAEL ODIN KIRKDALE Signature:

This inspection Report was submitted to CVSE on 2026-Mar-26 01:44 PM EDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection information, and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.