

Commercial Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GD93374 2025-Oct-31 21109464

Inspection Result: UAI-12

FACILITY:

CANADIAN TRUCK & TRAILER /

YAWNEY, MATTHEW WILLIAM HENRY / 108374

INSP. TYPE:

Complete

INSP. START:

2024-Oct-16 05:42 PM PDT

INSPECTOR: WORK ORDER #:

INSP. CLASS: INSP. REASON:

Class 3 - Trailer and Semi-Trailer

INSP. COMPLETE:

2024-Oct-16 06:42 PM PDT

VEHICLE JUR:

PLATE #:

MODEL .

276117

British Columbia

42319K

REGI-

14201472 3213

Van Traile:

Annual

VIN:

ADDRESS:

OWNER/LESSEE NAME:

1GRAA0629CD443972

VITRAN EXPRESS CANADA INC. VITRAN EXPRESS CANADA INC.

10077 GRACE ROAD, 10077 GRACE ROAD

Surrey, British Columbia V3V3V7, Canada

VEHICLE YEAR: MAKE:

LICENCED GVW(kg): 0

2012

GREAT DANE

BODY STYLE: ODOMETER:

UNIT/FLEET#:

HUB ODOMETER: BRAKE TYPE:

FUEL TYPE:

Vehicle Identification (VIN) Section 1 - Power Train

Section 2 - Suspension Section 3 - Brake System Section 3A- Air Brakes

Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary

Equipment

Section 6 - Lamps Section 7 - Electrical System Section 8 - Frame and Body Section 9A - Tires Section 9B - Wheels

Section 10 - Coupling Devices Section 11 - Other Vehicle Components Passed

Not Applicable Passed Passed

Passed Not Applicable Not Applicable

Not Applicable

Passed Passed Passed Passed Passed Passed

Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Left

0

0

Axles	Туре	Size	Slack Adj.	Left	Right
1	Disc	N/A	Not Applicable	0	0
2	Disc.	NA	Not Applicable	0	0
Comment:					

Right	1
0	
0	

Brake Lining/Pad (mm)

Lining/Pad

Pad

Pad

nent:		
	Right	

Tire Tread Depth (mm) Outer L

7.1

7 9

Com

Left

19

19

	Rotor Th
light	
19	
19	

Comment:

Inner L

7.9

7.9

ickness or Drum Inside Diameter (mm) Rotor/Drum

Inner R

7.9

127

Rotor

Rotor

Left Right 41.00 45.00 42.00 45.00

Steering

Outer R

7.9

127

Comment:

Inspector:

Axles

2

Inspection Comments:

Has this Vehicle been road tested?

Air Brake Camshaft Rotation (degrees)

No YAWNEY, MATTHEW WILLIAM

Right

0

0

Comment:

Signature:

HENRY

This inspection Report was submitted to CVSE on 2024-Oct-16 07:43 PM PDT.

The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

