

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: GC58796 2025-Sep-30 21058720

Inspection Result:

ISPECTOR: **/ORK ORDER #:**

ACILITY:

LOWER MAINLAND TRUCK / S6962 INSP. TYPE:

GILL, SANTOKH SINGH / 115080

INSP. CLASS: INSP. REASON: Complete Class 3 - Trailer and Semi-Trailer INSP. START: INSP. COMPLETE: 2024-Sep-03 07:00 AM PDT 2024-Sep-03 10:00 AM PDT

EHICLE JUR:

LATE #:

IAKE:

IODEL:

British Columbia

REGI:

14020788 53D082

Annual

VIN:

OWNER/LESSEE NAME:

CLARKE TRANSPORT INC, CLARKE

TRANSPORT INC

1UYVS25306G995041

ICENCED GVW(kg): 0

26700K

UNIT/FLEET#: **BODY STYLE:**

Van Trailer

ADDRESS:

201 WESTCREEK BLVD, 201

WESTCREEK BLVD

BRAMPTON, Ontario

I.6T5S6, Canada

EHICLE YEAR:

2006 UTILITY ODOMETER:

HUB ODOMETER:

BRAKE TYPE: Air

FUEL TYPE:

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Not Applicable Passed

Section 3 - Brake System Section 3A - Air Brakes

Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary

≘quipment Section 6 - Lamps

Section 9A - Tires

Section 7 - Electrical System

Section 8 - Frame and Body

Section 9B - Wheels Section 10 - Coupling Devices

Passed

Repaired (same day) REPLCE ABS VALVE AND ECU COMPLETE Passed

Not Applicable

Not Applicable Not Applicable

Passed

Repaired (same day) Repaired (same day) REPAIRED BROKEN 7 WIRE RECEPTACLE AND HOUSING REPAIR R/S DOOR HOLD-BACK

Passed Passed

Section 11 - Other Vehicle Components

Not Applicable

Passed

ır	Brake	Chamber	Type, Size	and I	Push	Rod	Stroke	(mm)
			.,,, -, -,					(,

ir Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	37	37	7.9	7.9	10.3	10.3	
2	Clamp	30	Automatic	37	37	7.1	7.1	5.6	5.6	
Comment:						Comment:				

ir Brake Camsha	ft Rotation (degr	ces)	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	68	70	Lining (Shoe)	14	14	Drum		· ·	
2	74	56	Lining (Shoe)	13	16	Drum	·		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation perform Thickness or Drum Diameter not measured.				

ispection Comments:

as this Vehicle been road tested? ispector:

GILL, SANTOKH SINGH

Road Test Date: Signature:

Road Tester:

his Inspection Report was submitted to CVSE on 2024-Sep-03 02:07 PMPD I

ne Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

OTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

to personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection d for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this formation, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement √SFΩ014

3/2024 2:07:32 PM PDT