



Commercial Vehicle Inspection Report

Decal Number: GL67055
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21629897

602-11
Inspection Result:
PASS

FACILITY: BRIGHT QUALITY ENTERPRISES LTD / S15780
INSPECTOR: JAGPAL, CHANDEEP SINGH / 202483
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Jan-13 09:00 AM PST
INSP. COMPLETE: 2026-Jan-13 12:30 PM PST

VEHICLE JUR: British Columbia
PLATE #: VF9053
LICENCED GVW(kg): 49000
VEHICLE YEAR: 2015
MAKE: INTERNATNA
MODEL:

REGI: 11064839
UNIT/FLEET#: 104
BODY STYLE: Truck Tractor
ODOMETER: 821960 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1HSDJAPR9FH520191
OWNER/LESSEE NAME: ALL TRACK TRANSPORT LTD, .
ADDRESS: 291-7184 120 STREET
Surrey, British Columbia
V3W3M8, Canada

Section	Result	Details
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Repaired (same day)	REPLACED #2/3 AXL TORQUE RODS
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REFIXED LEFT TAIL SIGNAL LAMP
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	33	33	6			6	✓
2	Clamp	30L	Automatic	34	33	10	10	7	7	
3	Clamp	30L	Automatic	33	34	14	14	14	14	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	46	46	Lining (Shoe)	15	15	Drum		
2	38	28	Lining (Shoe)	18	21	Drum		
3	31	31	Lining (Shoe)	21	21	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: JAGPAL CHANDEEP SINGH
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jan-14 03:23 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.