



# Commercial Vehicle Inspection Report

Decal Number: GL67002  
 Decal Expiry Date: 2026-Dec-31  
 Inspection Number: 21591833

Inspection Result: **PASS** *Kaa-1*

**FACILITY:** BRIGHT QUALITY ENTERPRISES LTD / S15780  
**INSPECTOR:** JAGPAL, CHANDEEP SINGH / 202483  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual  
**INSP. START:** 2025-Dec-03 04:00 PM PST  
**INSP. COMPLETE:** 2025-Dec-03 06:00 PM PST

**WORK ORDER #:**

**VEHICLE JUR:** British Columbia  
**PLATE #:** 53818K  
**LICENCED GWW(kg):** 0  
**VEHICLE YEAR:** 2024  
**MAKE:** TYCROP  
**MODEL:**  
**REGI:** 14541221  
**UNIT/FLEET#:** WF113  
**BODY STYLE:** Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 2T9YAAZC7RD016385  
**OWNER/LESSEE NAME:** ALL TRACK TRANSPORT LTD, ALL TRACK TRANSPORT LTD  
**ADDRESS:** 291-7184 120 ST  
 Surrey, British Columbia  
 V3W3M8, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) RETORQUE AIR BAGS BOTTOM MOUNT NUTS
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxilliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPLACED RIGHT SIDE MUDFLAP
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30L	Automatic	31	31	13	13	13	13	
2	Clamp	30L	Automatic	31	31	12	12	12	12	
3	Clamp	30L	Automatic	31	31	13	13	13	13	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	36	36	Lining (Shoe)	18	18	Drum		
2	40	40	Lining (Shoe)	18	18	Drum		
3	36	36	Lining (Shoe)	18	18	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

**Inspection Comments:**

Has this Vehicle been road tested? No  
 Inspector: JAGPAL, CHANDEEP SINGH  
 Road Test Date: \_\_\_\_\_  
 Signature:   
 Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2025-Dec-03 06:23 PMPST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement

CVSE0014

12/3/2025 6:23:26 PM PST